



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test June 9, 2010 Operator Elm Ridge Exploration API #30-039-82398

Property Name AXI Apache A Well No. 7 Location: Unit J Section 9 Township 23N Range 5W

Well Status (Shut-In or Producing) Initial PSI: Tubing 19 Intermediate NA Casing 75 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead Int	Csg	INTERM Int	Csg
TIME					
5 min	<u>0</u>		<u>75</u>		
10 min	<u>0</u>		<u>75</u>		
15 min	<u>0</u>		<u>75</u>		
20 min	<u>0</u>		<u>75</u>		
25 min	<u>0</u>		<u>75</u>		
30 min	<u>0</u>		<u>75</u>		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	<u>✓</u>
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS:

By Joe J. Luwata Jr.
Pumper
(Position)

Witness

E-mail address

