

5053270207

Benson-Montlin-Greer

03:37:34 p.m. 07-20-2010



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(805) 534-6170 FAX: (805) 534-6170
<http://nmnr.d.state.nm.us/ocd/District/IVS/dmrts.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 10/11/10 Operator Benson Montlin Greer API #30-0 39-05685

Property Name fed 17-32 Well No. 1 Location: Unit Section 32 Township 25N Range 1E

Well Status (Shut-In or Producing) Initial PSI: Tubing 10 Intermediate 44 Casing 7 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM.	
	BH	Int	Csg	Int	Csg
TIME					
5 min					
10 min					
15 min					
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD _____

INTERMEDIATE _____

REMARKS:

By Benson Montlin Greer

Witness _____

(Position)

E-mail address _____

