



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 10-26-10 Operator Robert C Bayless API #30-0 39-06213

Property Name Bolack Well No. 3 Location: Unit P Section 31 Township 76N Range 7W

Well Status(Shut-In or Producing) Initial PSI: Tubing 90 Intermediate Casing 150 Bradenhead 9 PSI

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
5 min	0		150		
10 min	0		150		
15 min	0		150		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	0 PSI
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS:

By Adrian Lozano

Witness

pumper
(Position)

E-mail address aguiss@r1bayless.com

