

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX: (505)334-6170

[http://emprd.state.nm.us/ocd/District III/3district.htm](http://emprd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT
(Submit 1 copy to above address)

Date of Test 7-20-2010 Operator Dugan Production Corp API # 30-039-05695
Property Name Kilgore Well No. 1 Location: Unit P Section 36 Township 25N Range 02W
Well Status(Shut-In or Producing) Initial PSI: Tubing 103.3 Intermediate — Casing 102.7 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURE						FLOW CHARACTERISTICS	
	Bradenhead			Interm			BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg			
5 minutes	0		103			Steady Flow		
10 minutes	0		102.9			Surges		
15 minutes	0		102.8			Down to Nothing		
20 minutes	0		102.8			Nothing	X	
25 minutes						Gas		
30 minutes						Gas & Water		
						Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____


5 MINUTE SHUT-IN

BRADENHEAD

0

INTERMEDIATE

REMARKS:



By

Carl D. Meek

Switcher

(Position)

Witness