

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

<http://emnr.state.nm.us/ocd/District/III/3disric.htm>

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 7-23-2010 Operator Dugan Production Corp API # 30-039-06000
Property Name Hurt Well No. 4 Location: Unit J Section 14 Township 25N Range 03W
Well Status (Shut-In or Producing) Initial PSI: Tubing 39.6 Intermediate _____ Casing 11 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

FLOW CHARACTERISTICS

TIME	Bradenhead Interm				FLOW CHARACTERISTICS	BRADENHEAD	INTERMEDIATE
	BH	Int	Int	Csg			
5 minutes	0	39.6			Steady Flow		
10 minutes	0	39.6			Surges		
15 minutes	0	39.6			Down to Nothing		
20 minutes	0	39.6			Nothing	X	
25 minutes					Gas		
30 minutes					Gas & Water		
					Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE _____

REMARKS: packer in well. Press taken on tubing string

By Carl A. Meek
Switcher
(Position)

Witness _____

