

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

<http://emnr.state.nm.us/ocd/District/III/3district.htm>

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 7-23-2010 Operator Dugan Production Corp API # 30-039-06032
Property Name Hurt Well No. 3 Location: Unit B Section 14 Township 25N Range 03W
Well Status (Shut-In or Producing) Initial PSI: Tubing 43.4 Intermediate — Casing 44 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURE					FLOW CHARACTERISTICS	
	Bradenhead		Interm			BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg		
5 minutes	0		44			Steady Flow	
10 minutes	0		44			Surges	
15 minutes	0		44			Down to Nothing	
20 minutes	0		43.9			Nothing	X
25 minutes						Gas	
30 minutes						Gas & Water	
						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN

BRADENHEAD

0

INTERMEDIATE

REMARKS:



By

Carl G. Meek

Witness

Switcher

(Position)