



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-19-10 Operator Noble Energy, Inc. API #30-0 3906750

Property Name Huron Well No. 3 Location: Unit E Section 5 Township 26 Range 4

Well Status (Shut-in or Producing) Initial PSI: Tubing 240 Intermediate Casing 240 Bradenhead 5

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					FLOW CHARACTERISTICS	
	Bradenhead		INTERM			BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int			
TIME							
5 min	<u>5</u>		<u>240</u>			Steady Flow	
10 min	<u>0</u>		<u>240</u>			Surges	
15 min	<u>0</u>		<u>240</u>			Down to Nothing <u>X</u>	
20 min	<u>0</u>		<u>240</u>			Nothing	
25 min	<u>0</u>		<u>240</u>			Gas	
30 min	<u>0</u>		<u>240</u>			Gas & Water	
						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE

REMARKS: Well shut in for rig work.



By Greg Vigil
lead pumper
(Position)

Witness

E-mail address