



NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 8-24-10 Operator Energen Resources API # 3003907782

Property Name SAN JUAN 30 4 UNIT 27 Location: Unit 0 Section 20 Township 30 Range 4
(Well Name and Number)

Pressure (Shut-in) or Producing) Tubing 150 Intermediate w/a Casing 200 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Intermediate	
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor	Flowed	Flowed
5 minutes	wo Blow	200		w/a		Steady Flow	w/a
10 minutes	wo Blow	200		w/a		Surges	w/a
15 minutes	wo Blow	200		w/a		Down to Nothing	w/a
20 minutes						No Flow	X
25 minutes						Gas	
30 minutes						Gas and Water	
5 minute SI						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead 0 Intermediate w/a

REMARKS:

By Al Graham Witness _____

(Position)

