

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

[http://emnrd.state.nm.us/ocd/District\\_III/3ddistrict.htm](http://emnrd.state.nm.us/ocd/District_III/3ddistrict.htm)

**BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

Date of Test 5-29-2010 Operator Dugan Production Corp API # 30-039-20197  
Property Name Nordhaus Well No 8 Location: Unit 1 Section 20 Township 25N Range 07W  
Well Status(Shut-In or Producing) Initial PSI: Tubing 95 Intermediate      Casing 95 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

FLOW CHARACTERISTICS

TIME	Bradenhead			Interm			FLOW CHARACTERISTICS	
	BH	Int	Csg	Int	Csg		BRADENHEAD	INTERMEDIATE
5 mintues	0		95			Steady Flow		
10 minutes	0		95			Surges		
15 minutes	0		95			Down to Nothing		
20 minutes						Nothing	✓	
25 minutes						Gas		
30 minutes						Gas & Water		
						Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_


5 MINUTE SHUT-IN

BRADENHEAD

0

INTERMEDIATE

REMARKS:



By

Ron Amador #31  
Switcher  
(Position)

Witness