

5053279207

Benson-Montlin-Greer

03:37:34 p.m. 07-20-2010



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(805) 334-0170 FAX: (805) 334-0170
<http://emnr.state.nm.us/od/District/USDistrict.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9/9/10 Operator Benson Montlin-Greer API #30-0 39-20352

Property Name CDU Well No. 17 Location: Unit G Section 1 Township 24N Range 1E

Well Status (Shut-In or Producing) Initial PSI: Tubing 370 Intermediate 414 Casing 372 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead				
	BH	Int	Csg	Int	Csg
TIME					
5 min					
10 min					
15 min					
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS

BRADENHEAD INTERMEDIATE

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD _____

INTERMEDIATE _____

REMARKS:

By: Ron J. Greer

Witness _____

(Position)

E-mail address _____

