

5053279207

Benson-Montlin-Greer

03:37:34 p.m. 07-20-2010

1/1



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1600 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-0170 FAX: (505) 334-0170
<http://omnrds.state.nm.us/load/District%203/district3.htm>

BRADENHEAD TEST REPORT


(submit 1 copy to above address)

Date of Test 9/9/10 Operator Benson Montlin Greer API #30-0 39-20426
Property Name COU Well No. 19 Location: Unit A Section 14 Township 27N Range 1W
Well Status (Shut-In or Producing) Initial PSI: Tubing 28 Intermediate 14 Casing 32 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead				
	BH	Int	Csg	Int	Csg
TIME					
5 min					
10 min					
15 min					
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	X	
Gas		
Gas & Water		
Water		



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD _____ INTERMEDIATE _____

REMARKS:

By Bert P. Greer

Witness _____

(Position)

E-mail address _____