



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 8-30-10 Operator Energen Resources API # 3003922210

Property Name SAN JUAN 30 4 UNIT 39 Location: Unit F Section 18 Township 30 Range 4
(Well Name and Number)

Pressure (Shut-in) or Producing) Tubing 115 Intermediate 0 Casing 160 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	<u>no blow</u>	<u>160</u>	<u>0</u>	<u>no blow</u>	<u>160</u>	Steady Flow	
10 minutes	<u>no blow</u>	<u>160</u>	<u>0</u>	<u>no blow</u>	<u>160</u>	Surges	
15 minutes	<u>no blow</u>	<u>160</u>	<u>0</u>	<u>no blow</u>	<u>160</u>	Down to Nothing	
20 minutes						No Flow	<u>X</u>
25 minutes						Gas	<u>X</u>
30 minutes						Gas and Water	
5 minute SI						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____

5 Minute Shut-in Bradenhead 0 Intermediate 0

REMARKS:

By Jeff Graham
Lease Operator
(Position)

Witness _____

