## NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District HI/3distric.htm

## **BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

Date of Test	7-10-10	Dugan Production Corp				API#	30-039-22634						
Property Name	Betty (	31	Well No.	2	_Location:	Unit	0	Section	31	Township	24N	Range	07W
Well Status(Sh	ut-In or Producing)	Initial PSI:	Tubing_	0	Intermedi	ia <u>te</u>	78	Casing	2		Bradeni	nead /	2
OPEN BRAI	DENHEAD AND PRESS Bradenhead		EDIATE 1	O ATMC	)SPHERE	E INDI		LY FOR		•	EACH		
TIME	BH Int Csg	!nt Csg	<del>-</del> 1				BRADE	ENHEAD		INTERME	DIATE	_	
5 mintues	0 3	`		Steady Flov	v,							_	
10 minutes				Surges								_	
15 minutes	0 2		1 .	Down to No	thing							-	
20 minutes			1	othing						·		-	
25 minutes				Gas								-	
30 minutes				Gas & Wate	ar		· · · · · · · · · · · · · · · · · · ·					-	
00 111111111111	L	·L	<b>-</b>	Nater	<b>5</b> 1							-	
If bradenhead flowed water, check all of the descriptions that apply below:  CLEAR FRESH SALTY SULFUR BLACK 28293037													
5 MINUTE S REMARKS:	SHUT-IN	BRADENHE	AD _	<i>\( \text{O} \)</i>		INTER	RMEDIATE			1007/222324 25. 25. 25. 25. 25. 25. 25. 25. 25. 25.	RECE ISBN 2 CONS. DI	IVED 1010 10131:3	2345678970
Ву	RN	(Vie)				Witne	99				7.017	-	
-,		Switcher (Position)	A-10		<del>-</del> -	VVILLIC			<u></u>			-	