

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

[http://emrmd.state.nm.us/ocd/District III/3district.htm](http://emrmd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 6-7-2016 Operator Dugan Production Corp API # 30-039-23001
Property Name Boomer Well No. 1 Location: Unit A Section 32 Township 25N Range 07W
Well Status(Shut-In or Producing) Initial PSI: Tubing 90 Intermediate _____ Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	<u>0</u>		<u>0</u>			
10 minutes						
15 minutes						
20 minutes						
25 minutes						
30 minutes						

FLOW CHARACTERISTICS

Steady Flow
Surges
Down to Nothing
Nothing
Gas
Gas & Water
Water

BRADENHEAD	INTERMEDIATE

If bradenhead flowed water, check all of the descriptions that apply below:


CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN

BRADENHEAD 0

INTERMEDIATE _____

REMARKS:



By

Ben Horale #31
Switcher
(Position)

Witness _____