

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

[http://emnr.state.nm.us/ocd/District III/3dislr.htm](http://emnr.state.nm.us/ocd/District%20III/3dislr.htm)

**BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

Date of Test 7-13-10 Operator Dugan Production Corp API # 30-039-24463  
Property Name Sapp C Well No. 4 Location: Unit 7 Section 5 Township 23N Range 07W  
Well Status(Shut-In or Producing) Initial PSI: Tubing 52 Intermediate 14 Casing 52 Bradenhead 4

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

FLOW CHARACTERISTICS

TIME	Bradenhead			Interm				FLOW CHARACTERISTICS	
	BH	Int	Csg	Int	Csg			BRADENHEAD	INTERMEDIATE
5 minutes	0		52				Steady Flow		
10 minutes							Surges		
15 minutes							Down to Nothing		
20 minutes	0		52				Nothing		
25 minutes							Gas		
30 minutes							Gas & Water		
							Water		

**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

**5 MINUTE SHUT-IN** BRADENHEAD 0 INTERMEDIATE \_\_\_\_\_

REMARKS:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

By Bolixé  
Switcher  
(Position)

Witness \_\_\_\_\_

