

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

[http://emnrd.state.nm.us/ocd/District\\_III/3distric.htm](http://emnrd.state.nm.us/ocd/District_III/3distric.htm)

**BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

Date of Test 7-9-10 Operator Dugan Production Corp API # 30-039-25510  
Property Name Sapp C Well No. 5 Location: Unit 9 Section 5 Township 23N Range 07W  
Well Status(Shut-In or Producing) Initial PSI: Tubing 40 Intermediate 0 Casing 40 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURE						FLOW CHARACTERISTICS	
	Bradenhead		Interm		BRADENHEAD		INTERMEDIATE	
	BH	Int	Csg	Int				Csg
5 minutes	0		40					
10 minutes								
15 minutes								
20 minutes	0		40					
25 minutes								
30 minutes								

Steady Flow  
Surges  
Down to Nothing  
Nothing  
Gas  
Gas & Water  
Water

**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR    FRESH    SALTY    SULFUR    BLACK   

**5 MINUTE SHUT-IN** BRADENHEAD 0 INTERMEDIATE   

REMARKS:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

By Bollive  
\_\_\_\_\_  
Switcher  
(Position)

Witness \_\_\_\_\_

