

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

<http://emnr.state.nm.us/ocd/District/III/3district.htm>

**BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

Date of Test 6-7-2010 Operator Dugan Production Corp API # 30-039-25739  
Property Name Mona Lisa Well No. 1 CH Location: Unit P Section 14 Township 26N Range 07W  
Well Status(Shut-In or Producing) Initial PSI: Tubing 50 Intermediate      Casing 60 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	<u>0</u>		<u>60</u>			
10 minutes	<u>0</u>		<u>60</u>			
15 minutes	<u>0</u>		<u>60</u>			
20 minutes						
25 minutes						
30 minutes						

FLOW CHARACTERISTICS

Steady Flow  
Surges  
Down to Nothing  
Nothing  
Gas  
Gas & Water  
Water

BRADENHEAD	INTERMEDIATE
<u>✓</u>	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR      FRESH      SALTY      SULFUR      BLACK     

5 MINUTE SHUT-IN

BRADENHEAD 0

INTERMEDIATE     

REMARKS:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

By Ron Hanch # 31 Witness       
\_\_\_\_\_  
Switcher  
(Position)

