



NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 8-25-10 Operator Energen Resources API # 3003926133

Property Name CARSON 5 Location: Unit B Section 30 Township 30 Range 4
(Well Name and Number)

Pressure (Shut-in) or Producing) Tubing 125 Intermediate N/A Casing 165 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	<u>no</u> <u>Blow</u>			<u>N/A</u>		Steady Flow	<u>N/A</u>
10 minutes	<u>no</u> <u>Blow</u>			<u>N/A</u>		Surges	<u>N/A</u>
15 minutes	<u>no</u> <u>Blow</u>			<u>N/A</u>		Down to Nothing	<u>N/A</u>
20 minutes						No Flow	<u>X</u>
25 minutes						Gas	
30 minutes						Gas and Water	
5 minute SI						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur Black

5 Minute Shut-in Bradenhead 0 Intermediate N/A

REMARKS:

By Jeff Graham Witness
Lease Operator
(Position)

