

NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410 (505 334-6178 FAX: (505) 334-6170 http://www.emnrd.state.nm.us/ocd/

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

			(it & copies to at		<i></i>		
Date of Test 8-27-		9-10 Operator		Energ	Energen Resources			3003926320
Property Name	e S/	SAN JUAN 3		Locatio	Location: Unit D		ownship	30 Range 4
		(Well Name	and Number)					
Pressure (Shu	it-in or Proc	lucing)	Tubing /	15 Interme	diate <u>w/</u>	Casing /	50 Bra	adenhead <u>O</u>
OPEN	BRADENHI	EAD AND	INTERMEDIA	TE TO ATMOSF	PHERE IND	IVIDUALLY FOR	15 MINUT	TES EACH
	Bradenhead			Interme	diate		Bradon	head Intermediate
<u>Time</u>	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flow	
5 minutes	Blow	150		w/w	Wolliton	Steady Flow		N/A-
10 minutes	WO Bbw	150		الفداا		Surges		N/A
15 minutes	NO Blow	150		W/4-		Down to Nothing		N/A
20 minutes	1510W	100		- 14		No Flow	\overline{X}	
25 minutes						Gas		
30 minutes						Gas and Water		
5 minute SI						Water		
If bradenhe Clear 5 Minute Sh	F	vater, che resh radenhea	Sa	lescriptions tha	t apply belo Sulfur ឃ/µ	<u>ow:</u> Bla	15	2010 - 123 9 50 10 10 10 10 10 10 10 10 10 10 10 10 10
		~~*****						
Ву	Leose (ham Denote (Position		Wi	tness			