

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

<http://emnr.state.nm.us/ocd/District/III/3district.htm>

**BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

Date of Test 7-9-10 Operator Dugan Production Corp API # 30-039-26372  
Property Name Mighty Corn Well No. 90 Location: Unit L Section 32 Township 24N Range 07W  
Well Status (Shut-In) Initial PSI: Tubing NA Intermediate            Casing 0 # Bradenhead 1 #

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	0		0			
10 minutes	0		0			
15 minutes	0		0			
20 minutes						
25 minutes						
30 minutes						

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

FLOW CHARACTERISTICS

BRADENHEAD

INTERMEDIATE

BRADENHEAD	INTERMEDIATE
✓	

**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR            FRESH            SALTY            SULFUR            BLACK           

**5 MINUTE SHUT-IN**

BRADENHEAD

0 #

INTERMEDIATE

REMARKS:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

By Bellure Switcher  
(Position)

Witness \_\_\_\_\_

