



NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 8-23-10 Operator Energen Resources API # 3003926609

Property Name SAN JUAN 30 4 UNIT 50 Location: Unit L Section 22 Township 30 Range 4
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 0 Intermediate N/A Casing 380 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate			Bradenhead Intermediate		
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed	
5 minutes	<u>No Blow</u>	<u>380</u>	<u>N/A</u>	<u>N/A</u>		Steady Flow		<u>N/A</u>	
10 minutes	<u>No Blow</u>	<u>380</u>	<u>N/A</u>	<u>N/A</u>		Surges		<u>N/A</u>	
15 minutes	<u>No Blow</u>	<u>380</u>	<u>N/A</u>	<u>N/A</u>		Down to Nothing		<u>N/A</u>	
20 minutes						No Flow	<u>X</u>		
25 minutes						Gas			
30 minutes						Gas and Water			
5 minute SI						Water			

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____

5 Minute Shut-in Bradenhead 0 Intermediate N/A

REMARKS:



By [Signature]
Lease Operator
(Position)

Witness _____