



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT
(Submit 2 copies to above address)

Date of Test 8-23-10 Operator Energen Resources API # 3003926883

Property Name SAN JUAN 30 4 UNIT 34R Location: Unit F Section 16 Township 30 Range 4
(Well Name and Number)

Pressure (Shut-in) or Producing Tubing 320 Intermediate w/# Casing 350 ~~320~~ Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate			Bradenhead	Intermediate
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed
5 minutes	<u>no Blow</u>	<u>350</u>		<u>w/A</u>		Steady Flow		<u>w/A</u>
10 minutes	<u>no Blow</u>	<u>350</u>		<u>w/A</u>		Surges		<u>w/A</u>
15 minutes	<u>no Blow</u>	<u>350</u>		<u>w/A</u>		Down to Nothing		<u>w/A</u>
20 minutes						No Flow	<u>X</u>	
25 minutes						Gas		
30 minutes						Gas and Water		
5 minute SI						Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____

5 Minute Shut-in Bradenhead 0 Intermediate w/A

REMARKS:

By

Jeff Graham
Lease Operator
(Position)

Witness

