

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX: (505)334-6170

<http://emvrd.state.nm.us/ocd/District/III/3distric.htm>

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 9-2-10 Operator Dugan Production Corp API # 30-043-20319
Property Name Dome Rusty 20-22-7 Well No. 1 Location: Unit P Section 20 Township 22N Range 07W
Well Status(Shut-In or Producing) Initial PSI: Tubing 105 Intermediate N/A Casing 130 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm	
	BH	Int	Csg	Int	Csg
5 minutes	<u>0</u>	<u>N/A</u>	<u>130</u>		
10 minutes	<u>0</u>	<u>N/A</u>	<u>130</u>		
15 minutes	<u>0</u>	<u>N/A</u>	<u>130</u>		
20 minutes					
25 minutes					
30 minutes					

FLOW CHARACTERISTICS

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

BRADENHEAD	INTERMEDIATE

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:



By

Curtis Davis

Witness

Switcher

(Position)