

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

[http://emard.state.nm.us/ocd/District III/3district.htm](http://emard.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 6-28-10 Operator Dugan Production Corp API # 30-043-20404
Property Name Dome Federal 19-22-6 Well No. 1 Location: Unit 4 Section 19 Township 22N Range 06W
Well Status(Shut-In or Producing) Initial PSI: Tubing 20 Intermediate N/A Casing 24 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURE					FLOW CHARACTERISTICS	
	Bradenhead	Interm				BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg		
5 minutes	<u>0</u>	<u>N/A</u>	<u>24</u>			Steady Flow	
10 minutes	<u>0</u>	<u>N/A</u>	<u>24</u>			Surges	
15 minutes	<u>0</u>	<u>N/A</u>	<u>24</u>			Down to Nothing	
20 minutes						Nothing	
25 minutes						Gas	
30 minutes						Gas & Water	
						Water	

If bradenhead flowed water, check all of the descriptions that apply below:


CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN

BRADENHEAD 0

INTERMEDIATE _____

REMARKS:



By

Curtis Davis

Witness _____

Switcher

(Position)