NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test	6-28/10	Operator	Dugan Production Corp				API#	30-043-20476				.	
Property Name	Dome Nava	o 28-22-6	Well No	44	_Location:	Unit	K	Section	28	Township	22N	Range	06W
Well Status(Shut-In or Producing) Initial PSI:			Tubing _	25	Intermedia	ate ${\cal N}$	1/A	Casing	2	9	Bradent	nead 🗲	9
Topography in the Control of the Con	DENHEAD AND PRESS Bradenhead BH Int Csg O MA 29 O MA 29 O MA 29) INTERME	DIATE 1	CO ATMC Steady Flow Surges Down to No	OSPHERE v		IDUAL		15 M	INUTES	EACH	-	
25 minutes				Nothing Gas								-	
30 minutes				Gas & Wate	er	, , , , , , , , , , , , , , , , , , , 						-	
				Nater								-	
If bradenhead flowed water, check all of the descriptions that apply below: CLEAR FRESH SALTY SULFUR BLACK 5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE REMARKS:													
5 MINUTE S	SHUT-IN	BRADENHEA	.D _	0		INTERN	/IEDIATE			(8)16,21.22.23.24.25.	REC SER CONS	EIVE 2010 DIV. DIST	23456789707 D 3 17
Ву	Switcher (Position)					VVitness	;	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,				•	