

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

http://emnr.state.nm.us/ocd/District_III/3district.htm

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 6-22-10 Operator Dugan Production Corp API # 30-043-20676
Property Name Ballymaloe Well No. 2 Location: Unit K Section 25 Township 23N Range 07W
Well Status(Shut-In or Producing) Initial PSI: Tubing 650 Intermediate 0 N/A Casing 650 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	<u>0</u>		<u>650</u>			
10 minutes	<u>0</u>		<u>650</u>			
15 minutes	<u>0</u>		<u>650</u>			
20 minutes						
25 minutes						
30 minutes						

FLOW CHARACTERISTICS

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

BRADENHEAD

INTERMEDIATE

If bradenhead flowed water, check all of the descriptions that apply below:


CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:



By

Curtis Davis
Switcher
(Position)

Witness _____