

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

<http://emnr.state.nm.us/ocd/District/III/3distric.htm>

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 6-28-10 Operator Dugan Production Corp API # 30-043-20988
Property Name Rusty Nail Com Well No 90 Location: Unit C Section 34 Township 22N Range 06W
Well Status (Shut-In or Producing) Initial PSI: Tubing 40 Intermediate N/A Casing 40 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

FLOW CHARACTERISTICS

TIME	Bradenhead			Intern			FLOW CHARACTERISTICS	
	BH	Int	Csg	Int	Csg		BRADENHEAD	INTERMEDIATE
5 minutes	<u>0</u>	<u>N/A</u>	<u>40</u>			Steady Flow		
10 minutes	<u>0</u>	<u>N/A</u>	<u>40</u>			Surges		
15 minutes	<u>0</u>	<u>N/A</u>	<u>40</u>			Down to Nothing		
20 minutes						Nothing		
25 minutes						Gas		
30 minutes						Gas & Water		
						Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE _____

REMARKS:



By

Curtis Davis
Switcher
(Position)

Witness _____