



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170

www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 1 copies to above address)

Date of Test 7-6-2010 Operator Noble Energy Inc. API #30-0
Property Name LINDA Well No. 31-27 Location: Unit 31 Township 27N Range 8W
Well Status (Shut-In or Producing) Tubing 140# Intermediate N/A Casing 150# Bradenhead 10#

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING		
5 minutes	<u>Ø</u>	<u>N/A</u>	<u>150#</u>	Steady Flow <u>NO</u>	<u>N/A</u>
10 minutes	<u>Ø</u>	<u>N/A</u>	<u>150#</u>	Surges <u>NO</u>	
15 minutes	<u>Ø</u>	<u>N/A</u>	<u>150#</u>	Down to Nothing <u>Yes</u>	
20 minutes	<u>Ø</u>	<u>N/A</u>	<u>150#</u>	Nothing <u>NO</u>	
25 minutes	<u>Ø</u>	<u>N/A</u>	<u>150#</u>	Gas <u>10# then Nothing</u>	
30 minutes	<u>Ø</u>	<u>N/A</u>	<u>150#</u>	Gas & Water <u>Very Little</u>	
				Water <u>clean</u>	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR X FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD X INTERMEDIATE _____

REMARKS:

this is A new well COULD BE
A Little water & Pressure From when well
was cemented? It HAD 10 psi shut in Pressure
Blew Right Down & there was A little Bit of

By Steven L. Southern
Pumper
(Position)

Witness _____

E-mail address ssouthern@nobleenergy.com Wipple but DIDN'T
Even Bubble

