



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 8-27-10 Operator Energen Resources API # 3003907840

Property Name SAN JUAN 30 4 UNIT 1 Location: Unit N Section 18 Township 30 Range 4
(Well Name and Number)

Pressure (Shut-in) or Producing) Tubing 145 Intermediate 0 Casing 170 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate			Bradenhead Intermediate		
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed	
5 minutes	<u>no Blow</u>	<u>170</u>	<u>0</u>	<u>no Blow</u>	<u>170</u>	Steady Flow			
10 minutes	<u>no Blow</u>	<u>170</u>	<u>0</u>	<u>no Blow</u>	<u>170</u>	Surges			
15 minutes	<u>no Blow</u>	<u>170</u>	<u>0</u>	<u>no Blow</u>	<u>170</u>	Down to Nothing			
20 minutes						No Flow	<u>X</u>	<u>X</u>	
25 minutes						Gas			
30 minutes						Gas and Water			
5 minute SI						Water			

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead 0 Intermediate 0

REMARKS:

By Jeff Graham
Lease Operator
(Position)

Witness _____