District I 1625 N. French Dr., Hobbs, NM 88240 District II

1301 W. Grand Ave., Artesia, NM 88210 District III 1000 Rio Brazos Rd., Aztec, NM 87410

State of New Mexico Energy Minerals and Natural Resources

> Department Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-144 July 21, 2008

For temporary pits, closed-loop sytems, and below-grade tanks, submit to the appropriate NMOCD District Office.

For permanent pits and exceptions submit to the Santa Fe

District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	Environmental Bureau office and provide a copy to the appropriate NMOCD District Office.
Pit, Closed-Loop System, Below-Grad	le Tank, or
Proposed Alternative Method Permit or Clos	sure Plan Application
Type of action: Permit of a pit, closed-loop system, below-grade to X Closure of a pit, closed-loop system, below-grade	
Modification to an existing permit	
Closure plan only submitted for an existing permit below-grade tank, or proposed alternative method	tted or non-permitted pit, closed-loop system,
Instructions: Please submit one application (Form C-144) per individual pit, closed-loo	p system, below-grade tank or alternative request
Please be advised that approval of this request does not relieve the operator of liability should operations renvironment. Nor does approval relieve the operator of its responsibility to comply with any other applicable	
Operator: ConocoPhillips Company	OGRID#: <u>217817</u>
Address: P.O. Box 4289, Farmington, NM 87499	
Facility or well name: SAN JUAN 30-5 UNIT 97M	
API Number: 30-039-30708 OCD Permit Number	er:
U/L or Qtr/Qtr: D(NW/NW) Section: 29 Township: 30N Range:	5W County: Rio Arriba
Center of Proposed Design: Latitude: 36.788981 °N Longitude:	107.387412 °W NAD: ☐ 1927 X 1983
Surface Owner: X Federal State Private Tribal Trust or India	
X Pit: Subsection F or G of 19.15.17.11 NMAC Temporary: X Drilling Workover Permanent Emergency Cavitation P&A X Lined Unlined Liner type: Thickness 20 mil X LLDPE X String-Reinforced Liner Seams: X Welded X Factory Other Volume: 7700	HDPE PVC 65 Other AN 2011 20 Other Ship Street Stre
notice of intent) Drying Pad Above Ground Steel Tanks Haul-off Bins Other	e activities which require prior approval of a permit or
Below-grade tank: Subsection I of 19.15.17.11 NMAC Volume: bbl Type of fluid: Tank Construction material: Secondary containment with leak detection Visible sidewalls, liner, 6-inch lift and auto Visible sidewalls and liner Visible sidewalls only Other Liner Type: Thickness mil HDPE PVC Other	omatic overflow shut-off
5 Alternative Method: Submittal of an exception request is required. Exceptions must be submitted to the Santa Fe Environ	mental Bureau office for consideration of approval.

Fencing: Subsection D of 19.15.17.11 NMAC (Applies to permanent pit, temporary pits, and below-grade tanks) Chain link, six feet in height, two strands of barbed wire at top (Required if located within 1000 feet of a permanent residence, school, hospital, inst Four foot height, four strands of barbed wire evenly spaced between one and four feet Alternate. Please specify Netting: Subsection E of 19.15.17.11 NMAC (Applies to permanent pits and permanent open top tanks)	itution or chui	rch)
Screen Netting Other Monthly inspections (If netting or screening is not physically feasible)		
8 Signs: Subsection C of 19.15.17.11 NMAC 12" X 24", 2" lettering, providing Operator's name, site location, and emergency telephone numbers X Signed in compliance with 19.15.3.103 NMAC		
Administrative Approvals and Exceptions: Justifications and/or demonstrations of equivalency are required. Please refer to 19.15.17 NMAC for guidance. Please check a box if one or more of the following is requested, if not leave blank: Administrative approval(s): Requests must be submitted to the appropriate division district of the Santa Fe Environmental Bureau office for consideration of approval. Exception(s): Requests must be submitted to the Santa Fe Environmental Bureau office for consideration of approval.	ideration of ap	pproval.
10		
Siting Criteria (regarding permitting): 19.15.17.10 NMAC Instructions: The applicant must demonstrate compliance for each siting criteria below in the application. Recommendations of acceptable source material are provided below. Requests regarding changes to certain siting criteria may require administrative approval from the appropriate district office or may be considered an exception which must be submitted to the Santa Fe Environmental Bureau Office for consideration of approval. Applicant must attach justification for request. Please refer to 19.15.17.10 NMAC for guidance. Siting criteria does not apply to drying pads or above grade-tanks associated with a closed-loop system.		
Ground water is less than 50 feet below the bottom of the temporary pit, permanent pit, or below-grade tank. - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	Yes	No
Within 300 feet of a continuously flowing watercourse, or 200 feet of any other watercourse, lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark). - Topographic map; Visual inspection (certification) of the proposed site	Yes	□No
Within 300 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application.	Yes	No
(Applies to temporary, emergency, or cavitation pits and below-grade tanks)	□NA	
 Visual inspection (certification) of the proposed site; Aerial photo; Satellite image Within 1000 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. 	Yes	No
(Applied to permanent pits)Visual inspection (certification) of the proposed site; Aerial photo; Satellite image	□NA	
Within 500 horizonal feet of a private, domestic fresh water well or spring that less than five households use for domestic or stock watering purposes, or within 1000 horizontal feet of any other fresh water well or spring, in existence at the time of initial application.	Yes	No
- NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site.		
Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance adopted pursuant to NMSA 1978, Section 3-27-3, as amended - Written confirmation or verification from the municipality; Written approval obtained from the municipality	Yes	No
Within 500 feet of a wetland.US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site	Yes	No
Within the area overlying a subsurface mine Written confirmation or verification or map from the NM EMNRD - Mining and Mineral Division	Yes	□No
Within an unstable area. - Engineering measures incorporated into the design; NM Bureau of Geology & Mineral Resources; USGS; NM Geological Society; Topographic map	Yes	No
Within a 100-year floodplain - FEMA map	Yes	No

Temporary Pits, Emergency Pits and Below-grade Tanks Permit Application Attachment Checklist: Subsection B of 19.15.17.9 NMAC
Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached.
Hydrogeologic Report (Below-grade Tanks) - based upon the requirements of Paragraph (4) of Subsection B of 19.15.17.9 NMAC
Hydrogeologic Data (Temporary and Emergency Pits) - based upon the requirements of Paragraph (2) of Subsection B of 19.15.17.9
Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC
Design Plan - based upon the appropriate requirements of 19.15.17.11 NMAC
Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC
Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19.15.17.9 NMAC and 19.15.17.13 NMAC
Previously Approved Design (attach copy of design) APIor Permit
Closed-loop Systems Permit Application Attachment Checklist: Subsection B of 19.15.17.9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached. Geologic and Hydrogeologic Data (only for on-site closure) - based upon the requirements of Paragraph (3) of Subsection B of 19.15.17.9
Siting Criteria Compliance Demonstrations (only for on-site closure) - based upon the appropriate requirements of 19.15.17.10 NMAC
Design Plan - based upon the appropriate requirements of 19.15.17.11 NMAC
Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC
Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19.15.17.9 NMAC and 19.15.17.13 NMAC
Previously Approved Design (attach copy of design) API
Previously Approved Operating and Maintenance Plan API
Permanent Pits Permit Application Checklist: Subsection B of 19.15.17.9 NMAC
Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached.
Hydrogeologic Report - based upon the requirements of Paragraph (I) of Subsection B of 19.15.17.9 NMAC
Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC
Climatological Factors Assessment
Certified Engineering Design Plans - based upon the appropriate requirements of 19.15.17.11 NMAC
Dike Protection and Structural Integrity Design: based upon the appropriate requirements of 19.15.17.11 NMAC
Leak Detection Design - based upon the appropriate requirements of 19.15.17.11 NMAC
Liner Specifications and Compatibility Assessment - based upon the appropriate requirements of 19.15.17.11 NMAC
Quality Control/Quality Assurance Construction and Installation Plan
Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC
Freeboard and Overtopping Prevention Plan - based upon the appropriate requirements of 19.15.17.11 NMAC
Nuisance or Hazardous Odors, including H2S, Prevention Plan
Emergency Response Plan
Oil Field Waste Stream Characterization
Monitoring and Inspection Plan
Erosion Control Plan Change Plan Local and the convenient and instance of Subsection Conf. 10.15.17.13.20 MAC and 10.15.17.13.20 MAC.
Closure Plan - based upon the appropriate requirements of Subsection C of 19.15.17.9 NMAC and 19.15.17.13 NMAC
Proposed Closure: 19.15.17.13 NMAC
Instructions: Please complete the applicable boxes, Boxes 14 through 18, in regards to the proposed closure plan.
Type: Drilling Workover Emergency Cavitation P&A Permanent Pit Below-grade Tank Closed-loop System
Waste Removal (Closed-loop systems only)
On-site Closure Method (only for temporary pits and closed-loop systems)
In-place Burial On-site Trench
Alternative Closure Method (Exceptions must be submitted to the Santa Fe Environmental Bureau for consideration)
15
Waste Excavation and Removal Closure Plan Checklist: (19.15.17.13 NMAC) Instructions: Each of the following items must be attached to the closure plan.
Please indicate, by a check mark in the box, that the documents are attached.
Protocols and Procedures - based upon the appropriate requirements of 19.15.17.13 NMAC
Confirmation Sampling Plan (if applicable) - based upon the appropriate requirements of Subsection F of 19.15.17.13 NMAC
Disposal Facility Name and Permit Number (for liquids, drilling fluids and drill cuttings)
Soil Backfill and Cover Design Specifications - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC
Re-vegetation Plan - based upon the appropriate requirements of Subsection 1 of 19.15.17.13 NMAC
Site Reclamation Plan - based upon the appropriate requirements of Subsection G of 19.15.17.13 NMAC

16				
<u>Waste Removal Closure For Closed-loop Systems That Utilize A</u> Instructions: Please identify the facility or facilities for the disposal facilities are required.	bove Ground Steel Tanks or Haul-off Bins Only: (19.15.17.13.D NMAC) of liquids, drilling fluids and drill cuttings. Use attachment if more than two	,		
Disposal Facility Name:	Disposal Facility Permit #:			
Disposal Facility Name:	Disposal Facility Permit #:			
Will any of the proposed closed-loop system operations and as Yes (If yes, please provide the information	sociated activities occur on or in areas that will not be used for future No.	service and		
Required for impacted areas which will not be used for future service Soil Backfill and Cover Design Specification - based u Re-vegetation Plan - based upon the appropriate requir Site Reclamation Plan - based upon the appropriate requires	pon the appropriate requirements of Subsection H of 19.15.17.13 NM ements of Subsection I of 19.15.17.13 NMAC	AC		
Site rectamation rian based upon the appropriate req	ancheris of Subsection (10) 17.15.17.15 (4)			
certain siting criteria may require administrative approval from the appro	9.15.17.10 NMAC in the closure plan. Recommendations of acceptable source material are provided opriate district office or may be considered an exception which must be submitted to so fequivalency are required. Please refer to 19.15.17.10 NMAC for guidance.			
Ground water is less than 50 feet below the bottom of the buri		Yes No		
- NM Office of the State Engineer - iWATERS database search	; USGS: Data obtained from nearby wells	L N/A		
Ground water is between 50 and 100 feet below the bottom of	the buried waste	Yes No		
- NM Office of the State Engineer - iWATERS database search	USGS; Data obtained from nearby wells	□N/A		
Ground water is more than 100 feet below the bottom of the b	uried waste.	Yes No		
- NM Office of the State Engineer - iWATERS database search	USGS; Data obtained from nearby wells	∏ _{N/A}		
Within 300 feet of a continuously flowing watercourse, or 200 feet o (measured from the ordinary high-water mark).	f any other significant watercourse or lakebed, sinkhole, or playa lake	Yes No		
- Topographic map; Visual inspection (certification) of the prop	osed site			
Within 300 feet from a permanent residence, school, hospital, institution - Visual inspection (certification) of the proposed site; Aerial pho	• •	Yes No		
·	spring that less than five households use for domestic or stock watering	Yes No		
purposes, or within 1000 horizontal fee of any other fresh water well - NM Office of the State Engineer - iWATERS database; Visual				
pursuant to NMSA 1978, Section 3-27-3, as amended. - Written confirmation or verification from the municipality; Wr		Yes No		
Within 500 feet of a wetland		Yes No		
- US Fish and Wildlife Wetland Identification map; Topographic	e map; Visual inspection (certification) of the proposed site			
Within the area overlying a subsurface mine.		Yes No		
- Written confiramtion or verification or map from the NM EMN	RD-Mining and Mineral Division			
Within an unstable area. - Engineering measures incorporated into the design: NM Burgar	of Geology & Mineral Resources; USGS; NM Geological Society;	Yes No		
Topographic map	1 of ocology & Millional Resoluters, 6505, MM Geological Society,			
Within a 100-year floodplain FEMA map		Yes No		
18				
On-Site Closure Plan Checklist: (19.15.17.13 NMAC) Ins by a check mark in the box, that the documents are attached	tructions: Each of the following items must bee attached to the clos l.	sure plan. Please indicate,		
Siting Criteria Compliance Demonstrations - based up	on the appropriate requirements of 19.15.17.10 NMAC			
Proof of Surface Owner Notice - based upon the appro	priate requirements of Subsection F of 19.15.17.13 NMAC			
Construction/Design Plan of Burial Trench (if applicable) based upon the appropriate requirements of 19.15.17.11 NMAC				
Construction/Design Plan of Temporary Pit (for in place burial of a drying pad) - based upon the appropriate requirements of 19.15.17.11 NMAC				
Protocols and Procedures - based upon the appropriate	·	c.		
	on the appropriate requirements of Subsection F of 19.15.17.13 NMA	.		
	oriate requirements of Subsection F of 19.15.17.13 NMAC	cannot be achieved		
Disposal Facility Name and Permit Number (for liquids, drilling fluids and drill cuttings or in case on-site closure standards cannot be achieved) Soil Cover Design - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC				
Re-vegetation Plan - based upon the appropriate requirements of Subsection 1 of 19.15.17.13 NMAC Site Reclamation Plan - based upon the appropriate requirements of Subsection G of 19.15.17.13 NMAC				
1 She kecamanon rian - based upon the appropriate rec	parements of subsection O 01 13.13.17.13 NIMAC			

Operator Application Certification: I hereby certify that the information submitted with this application is true, accurate and complete to the best of my knowledge and belief.
Name (Print): Title:
Signature: Date: e-mail address: Telephone:
c-man address.
20 OCD Approval: Permit Application (including closure plan) Closure Plan (only) OCD Conditions (see attachment) OCD Representative Signature: Approval Date: 2/7///
Title: OCD Permit Number:
Closure Report (required within 60 days of closure completion): Subsection K of 19.15.17.13 NMAC Instructions: Operators are required to obtain an approved closure plan prior to implementing any closure activities and submitting the closure report. The closure report is required to be submitted to the division within 60 days of the completion of the closure activities. Please do not complete this section of the form until an approved closure plan has been obtained and the closure activities have been completed. X Closure Completion Date: June 22, 2010
Closure Method: Waste Excavation and Removal X On-site Closure Method Alternative Closure Method Waste Removal (Closed-loop systems only) If different from approved plan, please explain.
23
Closure Report Regarding Waste Removal Closure For Closed-loop Systems That Utilize Above Ground Steel Tanks or Haul-off Bins Only: Instructions: Please identify the facility or facilities for where the liquids, drilling fluids and drill cuttings were disposed. Use attachment if more than two facilities
were utilized. Disposal Facility Name: Disposal Facility Permit Number:
Disposal Facility Name: Disposal Facility Permit Number:
Were the closed-loop system operations and associated activities performed on or in areas that will not be used for future service and operations?
Yes (If yes, please demonstrate compliane to the items below)
Required for impacted areas which will not be used for future service and operations: Site Reclamation (Photo Documentation)
Soil Backfilling and Cover Installation
Re-vegetation Application Rates and Seeding Technique
Closure Report Attachment Checklist: Instructions: Each of the following items must be attached to the closure report. Please indicate, by a check mark in the box, that the documents are attached. X Proof of Closure Notice (surface owner and division) X Proof of Deed Notice (required for on-site closure) X Plot Plan (for on-site closures and temporary pits) X Confirmation Sampling Analytical Results (if applicable) Waste Material Sampling Analytical Results (if applicable) X Disposal Facility Name and Permit Number
X Soil Backfilling and Cover Installation
X Re-vegetation Application Rates and Seeding Technique X Site Reclamation (Photo Documentation)
[X] Site Reclamation (Photo Documentation) On-site Closure Location: Latitude: 36.78888 °N Longitude: 107.38731 °W NAD 1927 X 1983
77 John State Communication of the Communication of
25 Operator Closure Certification: I hereby certify that the information and attachments submitted with this closure report is ture, accurate and complete to the best of my knowledge and belief. I also certify that the closure complies with all applicable closure requirements and conditions specified in the approved closure plan.
Name (Print): Crystal Tafoya Title: Staff Regulatory Technician
Signature: Listal Taloya Date: 1/26/11
e-mail address: <u>crystal.tafoya@conocophillips.com</u> Telephone: 505-326-9837

ConocoPhillips Company San Juan Basin Closure Report

Lease Name: San Juan 30-5 Unit 97M

API No.: 30-039-30708

In accordance with Rule 19.15.17.13 NMAC the following information describes the closure of the temporary pit referenced above. All proper documentation regarding closure activities is being included with the C-144. The temporary pit for this location was constructed and location drilled before June 16, 2008 (effective date for Rule 19.15.17). While closure of the temporary pit did fall within the rule some dates for submittals are after the rig release date.

- Details on Capping and Covering, where applicable. (See report)
- Plot Plan (Pit Diagram) (Included as an attachment)
- Inspection Reports (Included as an attachment)
- Sampling Results (Included as an attachment)
- C-105 (Included as an attachment)
- Copy of Deed Notice will be filed with County Clerk (Not required on Federal, State, or Tribal land as stated by FAQ dated October 30, 2008)

General Plan:

1. All free standing liquids will be removed at the start of the pit closure process from the pit and disposed of in a division—approved facility or recycle, reuse or reclaim the liquids in a manner that the appropriate division district office approves.

All recovered liquids were disposed of at Basin Disposal (Permit #NM-01-005) and any sludge or soil required to be removed to facilitate closure was hauled to Envirotech Land Farm (Permit #NM-01-011) and JFJ Landfarm % IEI (Permit #NM-01-0010B).

2. The preferred method of closure for all temporary pits will be on-site burial, assuming that all the criteria listed in sub-section (B) of 19.15.17.13 are met.

The pit was closed using onsite burial.

3. The surface owner shall be notified of COPC's closing of the temporary pit as per the approved closure plan using certified mail, return receipt requested.

The closure process notification to the landowner was sent via email. (See Attached)(Well located on Federal Land, certified mail is not required for Federal Land per BLM/OCD MOU.)

4. Within 6 months of the Rig Off status occurring COPC will ensure that temporary pits are closed, re-contoured, and reseeded.

Provision 4 of the closure plan requirements were not met due to rig move off date as noted on C-105 which was prior to pit rule change. ConocoPhillips will ensure compliance with this rule in the future.

- 5. Notice of Closure will be given to the Aztec Division office between 72 hours and one week of closure via email, or verbally. The notification of closure will include the following:
 - i. Operator's name
 - ii. Location by Unit Letter, Section, Township, and Range. Well name and API number.

Notification is attached.

6. Liner of temporary pit shall be removed above "mud level" after stabilization. Removal of liner will consist of manually or mechanically cutting liner at mud level and removing all remaining liner. Care will be taken to remove "All" of the liner i.e., edges of liner entrenched or buried. All excessive liner will be disposed of at a licensed disposal facility.

Liner of temporary pit was removed above "mud level" after stabilization. Removal of the liner consisted of manually cutting liner at mud level and removing all remaining liner. Care was taken to remove "ALL" of the liner i.e., edges of liner entrenched or buried. All excessive liner was disposed of at a licensed disposal facility, (San Juan County Landfill).

7. Pit contents shall be mixed with non-waste containing, earthen material in order to achieve the solidification process. The solidification process will be accomplished using a combination of natural drying and mechanically mixing. Pit contents will be mixed with non-waste, earthen material to a consistency that is deemed a safe and stable. The mixing ratio shall not exceed 3 parts clean soil to 1 part pit contents.

ConocoPhillips mixed the Pit contents with non-waste containing, earthen material in order to achieve the solidification process. The solidification process was accomplished by using a combination of natural drying and mechanically mixing. Pit contents were mixed with non-waste, earthen material to a consistency that is deemed as safe and stable. The mixing ratio consisted of approximately 3 parts clean soil to 1 part pit contents.

8. A five point composite sample will be taken of the pit using sampling tools and all samples tested per Subsection B of 19.15.17.13(B)(1)(b). In the event that the criteria are not met, all contents will be handled per Subparagraph (a) of Paragraph (1) of Subsection B of 19.15.17.13 i.e., Dig and haul.

A five point composite sample was taken of the pit using sampling tools and all samples tested per Subsection B of 19.15.17.1 3(B)(1)(b). (Sample results attached).

Components	Tests Method	Limit (mg/Kg)	Results
Benzene	EPA SW-846 8021B or 8260B	0.2	2.4 ug/kg
BTEX	EPA SW-846 8021B or 8260B	50	34.7 ug/kG
TPH	EPA SW-846 418.1	2500	203 mg/kg
GRO/DRO	EPA SW-846 8015M	500	18.3 mg/Kg
Chlorides	EPA 300.1	1000(500)	150 mg/L

9. Upon completion of solidification and testing standards being passed, the pit area will be backfilled with compacted, non-waste containing, earthen material. A minimum of four feet of cover shall be achieved and the cover shall include one foot of suitable material to establish vegetation at the site, or the background thickness of topsoil, whichever is greater. If standard testing fails BR will dig and haul all contents pursuant to 19.15.17.13.i.a. After doing such, confirmation sampling will be conducted to ensure a release has not occurred.

The pit material passed solidification and testing standards. The pit area was then backfilled with compacted, non-waste containing, earthen material. More than four feet of cover was achieved and the cover included one foot of suitable material to establish vegetation at the site.

10. During the stabilization process if the liner is ripped by equipment the Aztec OCD office will be notified within 48 hours and the liner will be repaired if possible. If the liner can not be repaired then all contents will be excavated and removed.

The integrity of the liner was not damaged in the pit closure process.

11. Dig and Haul Material will be transported to the Envirotech Land Farm located 16 miles south of Bloomfield on Angel Peak Road, CR 7175. Permit # NM010011

Dig and Haul was not required.

12. Re-contouring of location will match fit, shape, line, form and texture of the surrounding. Re-shaping will include drainage control, prevent ponding, and prevent erosion. Natural drainages will be unimpeded and water bars and/or silt traps will be place in areas where needed to prevent erosion on a large scale. Final recontour shall have a uniform appearance with smooth surface, fitting the natural landscape.

The pit area was re-contoured to match fit, shape, line, form and texture of the surrounding area. Reshaping included drainage control, to prevent ponding and erosion. Natural drainages were unimpeded and water bars and/or silt traps were placed in areas where needed to prevent erosion on a large scale. Final recontour has a uniform appearance with smooth surface, fitting the natural landscape.

13. Notification will be sent to OCD when the reclaimed area is seeded.

Provision 13 was accomplished through complying with BLM seeding requirements as allowed by the BLM/OCD MOU.

14. COPC shall seed the disturbed areas the first growing season after the operator closes the pit. Seeding will be accomplished via drilling on the contour whenever practical or by other division-approved methods. BLM or Forest Service stipulated seed mixes will used on federal lands. Vegetative cover will equal 70% of the native perennial vegetative cover (un-impacted) consisting of at least three native plant species, including at least one grass, but not including noxious weeds, and maintain that cover through two successive growing seasons. Repeat seeding or planting will be continued until successful vegetative growth occurs.

Provision 14 was accomplished through complying with BLM seeding requirements as allowed by the BLM/OCD MOU.

15. The temporary pit will be located with a steel marker, no less than four inches in diameter, cemented in a hole three feet deep in the center of the onsite burial upon the abandonment of all the wells on the pad. The marker will be flush with the ground to allow access of the active well pad and for safety concerns. The marker will include a threaded collar to be used for future abandonment. The top of the marker will contain a welded steel 12" square plate that indicates the onsite burial of the temporary pit. The plate will be easily removable and a four foot tall riser will be threaded into the top of the collar marker and welded around the base with the operator's information at the time of all wells on the pad are abandoned. The operator's information will include the following: Operator Name, Lease Name, Well Name and number, Unit Number, Section, Township, Range and an indicator that the marker is an onsite burial location.

Provision 15 was accomplished by installing a steel marker in the temporary pit, no less than four inches in diameter, cemented in a hole three feet deep in the center of the onsite burial. The marker is flush with the ground to allow access of the active well pad and for safety concerns. The top of the marker contains a welded steel 12" square plate that indicates the onsite burial of the temporary pit. The plate contains the following: Operator Name, Lease Name, Well Name and number, Unit Number, Section, Township, Range and an indicator that the marker is an onsite burial location.

The plate will be easily removable and a four foot tall riser will be threaded into the top of the collar marker and welded around the base with the following operator's information at the time of all wells on the pad are abandoned. The riser will be labeled: COP, BLM, SJ 30-5 #97M, UL-D, Sec. 29, T 30N, R 5W, API # 30-039-30708

Sessions, Tamra D

From:

Sessions, Tamra D

Sent:

Wednesday, March 18, 2009 10:48 AM

To:

'mark_kelly@nm.blm.gov'

Subject:

Surface Owner Notification

The following temporary pits will be closed on-site. The new OCD Pit Rule 17 requires the surface owner be notified.

San Juan 31-6 Unit 27M

San Juan 32-7 Unit 18M

San Juan 32-7 Unit 71A

The following locations will have a temporary pit that will be closed on-site.

San Juan 28-6 Unit 109N

San Juan 28-6 Unit 126N

San Juan 28-6 Unit 144N

San Juan 29-6 Unit 4M

San Juan 29-7 Unit 83B

San Juan 29-7 Unit 83M

San Juan 30-5 Unit 97M

San Juan 30-5 Unit 100N

Thank You,

Tamra Sessions
Staff Regulatory Technician
CONOCOPHILLIPS COMPANY / SJBU
505-326-9834
Tamra.D.Sessions@conocophillips.com

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410

1220 S. St Francis Dr., Santa Fe, NM 87505

District IV

State of New Mexico
Energy, Minerals & Natural Resources Department
OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-102 Revised October 12, 2005 Submit to Appropriate District Office State Lease - 7 Copies Fee Lease - 3 Copies


☐ AMENDED REPORT

WELL LOCATION AND ACREAGE DEDICATION PLAT

l ,	API Number		2	Pool Code		3 Pool Name BASIN DAKOTA / BLANCO MESAV			ERDE
⁴ Property Co	de		- '		⁵ Proper SAN JUAN	ly Name N 30-5 UNIT			⁶ Well Number 97M
⁷ OGRID N	ľo –	_		C	8 Operator Name CONOCOPHILLIPS COMPANY			·	
· · · · · · · · · · · · · · · · · · ·					10 SURFACE	LOCATION			
UL or lot no.	Section 29	Township 30-N	Range 5-W	Lot Idn	Feet from the 690	North/South line NORTH	Feet from the 665	East/West line WEST	County RIO ARRIBA
		-	¹¹ E	ottom H	ole Location	If Different Fro	m Surface	<u> </u>	
UL or lot no.	Section	Township	Range	Lot Idn	Feet from the	North/South line	Feet from the	East/West line	County
Dedicated Acre 320.0 (DK-N/2 320.0 (MV-W/	2)	or Infill	Consolidation	Code 15	Order No	<u>.l , </u>	1	1	<u> </u>

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD LINIT HAS BEEN APPROVED BY THE DIVISION

	ONSOLDATED OR A	NON-STANDARD UNIT I	AS DEEN AFFR	OVED B1	THE DIVISION
XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	36.788981° N G: 107.387412° W		5279.5' (M) 5266.8' (R)	GLO 1916	17 OPERATOR CERTIFICATION I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief, and that this organization either owns a working interest or unleased mineral interest in the land including the proposed bottom hole location or has a right to drill this well at this location pursuant to a contract with an owner of such a mineral or working interest, or to a voluntary pooling agreement or a compulsory pooling order heretofore entered by the division
N 0'12'22" W N 0'01' E		N/2 DEDICATI USA SF			Signature Printed Name Title and E-mail Address Date 18 SURVEYOR CERTIFICATION
GLO 1916 W/2 DEDICATED USA SF-07 SECTION T-30-N, R-	78740 I 29,				I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my helief Date of Survey: 7/23/08 Signature and Seal of Professional Surveyor:
					Certificate Number: NM 11393



- 1. RESERVE PIT DIKE: TO BE 8' ABOVE DEEP SIDE (OVERFLOW-3' WIDE AND 1' ABOVE SHALLOW SIDE).
- 2. C.C.I. SURVEYS IS NOT LIABLE FOR UNDERGROUND UTILITIES OR PIPELINES.
 CONTRACTOR SHOULD CALL ONE-CALL FOR LOCATION OF ANY MARKED OR UNMARKED BURIED
- PIPELINES OR CABLES ON WELL PAD AND OR ACCESS ROAD AT LEAST TWO (2) WORKING DAYS PRIOR TO CONSTRUCTION.



EPA METHOD 8015 Modified Nonhalogenated Volatile Organics **Total Petroleum Hydrocarbons**

Client:	ConocoPhillips	Project #:	96052-1706
Sample ID:	Background	Date Reported:	05-10-10
Laboratory Number:	54040	Date Sampled:	05-05-10
Chain of Custody No:	9254	Date Received:	05-05-10
Sample Matrix:	Soil	Date Extracted:	05-07-10
Preservative:	Cool	Date Analyzed:	05-07-10
Condition:	Intact	Analysis Requested:	8015 TPH

Parameter	Concentration (mg/Kg)	Det. Limit (mg/Kg)
Gasoline Range (C5 - C10)	ND	0.2
Diesel Range (C10 - C28)	ND	0.1
Total Petroleum Hydrocarbons	ND	0.2

ND - Parameter not detected at the stated detection limit.

References:

Method 8015B, Nonhalogenated Volatile Organics, Test Methods for Evaluating Solid Waste,

SW-846, USEPA, December 1996.

Comments:

S.J. 30-5 #97M



EPA METHOD 8015 Modified Nonhalogenated Volatile Organics **Total Petroleum Hydrocarbons**

Client:	ConocoPhillips	Project #:	96052-1706
Sample ID:	Reserve Pit	Date Reported:	05-10-10
Laboratory Number:	54041	Date Sampled:	05-05-10
Chain of Custody No:	9254	Date Received:	05-05-10
Sample Matrix:	Soil	Date Extracted:	05-07-10
Preservative:	Cool	Date Analyzed:	05-07-10
Condition:	Intact	Analysis Requested:	8015 TPH

Parameter	Concentration (mg/Kg)	Det. Limit (mg/Kg)
Gasoline Range (C5 - C10)	ND	0.2
Diesel Range (C10 - C28)	18.3	0.1
Total Petroleum Hydrocarbons	18.3	0.2

ND - Parameter not detected at the stated detection limit.

References:

Method 8015B, Nonhalogenated Volatile Organics, Test Methods for Evaluating Solid Waste,

SW-846, USEPA, December 1996.

Comments:

S.J. 30-5 #97M



EPA Method 8015 Modified Nonhalogenated Volatile Organics Total Petroleum Hydrocarbons

Quality Assurance Report

Olient	04/00		D-1-14		11/0
Client:	QA/QC		Project #:		N/A
Sample ID:	05-07-10 QA/	QC	Date Reported:		05-10-10
Laboratory Number:	54015		Date Sampled:		N/A
Sample Matrix:	Methylene Chlo	ride	Date Received:		N/A
Preservative:	N/A		Date Analyzed:		05-07-10
Condition:	N/A		Analysis Reque	ested:	TPH
	: l≛Cal Date	I-Cal RF:	C Cal RF	% Difference	Accept Range
Gasoline Range C5 - C10	05-07-07	1.0645E+003	1.0649E+003	0.04%	0 - 15%
Diesel Range C10 - C28	05-07-07	1.0278E+003	1.0282E+003	0.04%	0 - 15%
Blank Conc. (mg/L - mg/Kg)	Concentration		Detection Limit	
Gasoline Range C5 - C10		ND		0.2	
Diesel Range C10 - C28		ND		0.1	
Total Petroleum Hydrocarbons		ND		0.2	
	ver en				
Duplicate Conc. (mg/Kg)	Sample	Duplicate	% Difference	Accept. Range:	
Gasoline Range C5 - C10	ND	ND	0.0%	0 - 30%	
Diesel Range C10 - C28	ND	ND	0.0%	0 - 30%	
Spike Conc. (mg/Kg)	Sample :	Spike Added	Spike Result	% Recovery	Accept: Range
Gasoline Range C5 - C10	ND	250	253	101%	75 - 125%
Diesel Range C10 - C28	ND	250	256	102%	75 - 125%

ND - Parameter not detected at the stated detection limit.

References:

Method 8015B, Nonhalogenated Volatile Organics, Test Methods for Evaluating Solid Waste,

SW-846, USEPA, December 1996.

Comments:

QA/QC for Samples 54015 - 54016 and 54038 - 54045.

Marchy Jan Re



EPA METHOD 8021 AROMATIC VOLATILE ORGANICS

Client:	ConocoPhillips	Project #:	96052-1706
Sample ID: .	Background ,	Date Reported:	05-10-10
Laboratory Number:	54040	Date Sampled:	05-05-10
Chain of Custody:	9254	Date Received:	05-05-10
Sample Matrix:	Soil	Date Analyzed:	05-07-10
Preservative:	Cool	Date Extracted:	05-07-10
Condition:	Intact	Analysis Requested:	BTEX

Parameter	Concentration (ug/Kg)	Det. Limit (ug/Kg)	
Dames	ND	0.0	
Benzene Toluene	ND ND	0.9 1.0	
Ethylbenzene	ND	1.0	
p,m-Xylene	ND	1.2	
o-Xylene	ND	0.9	
Total BTEX	ND		

ND - Parameter not detected at the stated detection limit.

Surrogate Recoveries:	Parameter	Percent Recovery
Name of the state	Fluorobenzene	92.6 %
	1,4-difluorobenzene	94.9 %
	Bromochlorobenzene	93.7 %

References:

Method 5030B, Purge-and-Trap, Test Methods for Evaluating Solid Waste, SW-846, USEPA,

December 1996.

Method 8021B, Aromatic Volatile Organics, Test Methods for Evaluating Solid Waste, SW-846,

USEPA, December 1996.

Comments:

S.J. 30-5 #97M

Branda Julian

Mustum Wolden
Review



EPA METHOD 8021 AROMATIC VOLATILE ORGANICS

	Client: Sample ID: Laboratory Number: Chain of Custody:	ConocoPhillips Reserve Pit , 54041 9254	Project #: Date Reported: Date Sampled: Date Received:	96052-1706 05-10-10 05-05-10 05-05-10
D // D / D / D / D / D / D / D / D / D	Sample Matrix:	Soil	Date Analyzed:	05-07-10
Preservative: Cool Date Extracted: U5-07-10 Condition: Intact Analysis Requested: BTEX	Preservative:	Cool	Date Extracted:	05-07-10

Parameter	Concentration (ug/Kg)	Det. Limit (ug/Kg)	
Benzene	2.4	0.9	
Toluene	16.5	1.0	
Ethylbenzene	1.2	1.0	
p,m-Xylene	11.3	1.2	
o-Xylene	3.3	0.9	
Total BTEX	34.7		

ND - Parameter not detected at the stated detection limit.

Surrogate Recoveries:	Parameter	Percent Recovery
	Fluorobenzene	91.4 %
	1,4-difluorobenzene	90.7 %
	Bromochlorobenzene	90.3 %

References:

Method 5030B, Purge-and-Trap, Test Methods for Evaluating Solid Waste, SW-846, USEPA,

December 1996.

Method 8021B, Aromatic Volatile Organics, Test Methods for Evaluating Solid Waste, SW-846,

USEPA, December 1996.

Comments:

S.J. 30-5 #97M

Analyst July

Mustum Walters
Review



EPA METHOD 8021 AROMATIC VOLATILE ORGANICS

Client:	N/A	Project #:	N/A
Sample ID:	05-07-BTX QA/QC	Date Reported:	05-10-10
Laboratory Number:	54015	Date Sampled:	N/A
Sample Matrix:	Soil	Date Received:	N/A
Preservative:	N/A	Date Analyzed:	05-07-10
Condition:	N/A	Analysis:	BTEX

Calibration and Detection Limits (ug/L)				≥ -= Blank Conc	
Benzene	1.2972E+006	1.2998E+006	0.2%	ND	0.1
Toluene	1.2007E+006	1.2031E+006	0.2%	ND	0.1
Ethylbenzene	1.0727E+006	1.0749E+006	0.2%	ND	0.1
p,m-Xylene	2.6560E+006	2.6613E+006	0.2%	ND	0.1
o-Xylene	1.0175E+006	1.0196E+006	0.2%	ND	0.1

Duplicate Conc. (ug/Kg)	Sample Du	plicate	%Diff.	Accept Range	Defect Limit
Benzene	ND	ND	0.0%	0 - 30%	0.9
Toluene	ND	ND	0.0%	0 - 30%	1.0
Ethylbenzene	ND	ND	0.0%	0 - 30%	1.0
p,m-Xylene	ND	ND	0.0%	0 - 30%	1.2
o-Xylene	ND	ND	0.0%	0 - 30%	0.9

Spike Conc. (ug/Kg)	Sample Amo	unt Spiked - Spik	ed Sample	% Recovery	Accept Range
Benzene	ND	50.0	48.1	96.2%	39 - 150
Toluene	ND	50.0	48.3	96.6%	46 - 148
Ethylbenzene	ND	50.0	47.5	95.0%	32 - 160
p,m-Xylene	ND	100	95.4	95.4%	46 - 148
o-Xylene	ND	50.0	47.7	95.4%	46 - 148

ND - Parameter not detected at the stated detection limit.

References:

Method 5030B, Purge-and-Trap, Test Methods for Evaluating Solid Waste, SW-846, USEPA,

December 1996.

Method 8021B, Aromatic and Halogenated Volatiles by Gas Chromatography Using Photoionization and/or Electrolytic Conductivity Detectors, SW-846, USEPA December 1996.

Comments:

QA/QC for Samples 54015 - 54016 and 54038 - 54045.

Sat Pay



EPA METHOD 418.1 TOTAL PETROLEUM HYDROCARBONS

Client:	ConocoPhillips	Project #:	96052-1706
Sample ID:	Background	Date Reported:	05-10-10
Laboratory Number:	54040	Date Sampled:	05-05-10
Chain of Custody No:	9254	Date Received:	05-05-10
Sample Matrix:	Soil	Date Extracted:	05-07-10
Preservative:	Cool	Date Analyzed:	05-07-10
Condition:	Intact	Analysis Needed:	TPH-418.1

		Det.
	Concentration	Limit
Parameter	(mg/kg)	(mg/kg)

Total Petroleum Hydrocarbons

29.8

21.6

ND = Parameter not detected at the stated detection limit.

References:

Method 418.1, Petroleum Hydrocarbons, Total Recoverable, Chemical Analysis of Water

and Waste, USEPA Storet No. 4551, 1978.

Comments:

S.J. 30-5 #97M



EPA METHOD 418.1 TOTAL PETROLEUM HYDROCARBONS

Client:	ConocoPhillips	Project #:	96052-1706
Sample ID: `	Reserve Pit	Date Reported:	05-10-10
Laboratory Number:	54041	Date Sampled:	05-05-10
Chain of Custody No:	9254	Date Received:	05-05-10
Sample Matrix:	Soil	Date Extracted:	05-07-10
Preservative:	Cool	Date Analyzed:	05-07-10
Condition:	Intact	Analysis Needed:	TPH-418.1

		Det.
	Concentration	Limit
Parameter	(mg/kg)	(mg/kg)

Total Petroleum Hydrocarbons

203

21.6

ND = Parameter not detected at the stated detection limit.

References:

Method 418.1, Petroleum Hydrocarbons, Total Recoverable, Chemical Analysis of Water

and Waste, USEPA Storet No. 4551, 1978.

Comments:

S.J. 30-5 #97M

Analyst

Mustum Waller Review



EPA METHOD 418.1 TOTAL PETROLEUM HYROCARBONS QUALITY ASSURANCE REPORT

Client:	QA/QC	Project #: Date Reported: Date Sampled:	N/A
Sample ID:	QA/QC		05-07-10
Laboratory Number:	05-07-TPH.QA/QC 54038		N/A
Sample Matrix: Preservative:	Freon-113	Date Analyzed:	05-07-10
	N/A	Date Extracted:	05-07-10
Condition:	N/A	Analysis Needed:	TPH

Calibration	I-Cal Date	C-Cal Date	I-Cal RF:	C-Cal RF:	% Difference	Accept. Range
'	04/22/2010	05-07-10	1,690	1,720	1.8%	+/- 10%

Blank Conc. (mg/Kg) TPH	Co	ncentration ND	ron service de la companya de la co	Detection Limi 21.6	t
Duplicate Conc. (mg/Kg) TPH		Sample 24.3	Duplicate 25.7	% Difference 5.8%	Accept. Range +/- 30%
Spike Conc. (mg/Kg) TPH	Sample Sp 24.3	oike Added 2,000	Spike Result 1,790	% Recovery 88.4%	Accept Range 80 - 120%

ND = Parameter not detected at the stated detection limit.

References:

Method 418.1, Petroleum Hydrocarbons, Total Recoverable, Chemical Analysis of Water

and Waste, USEPA Storet No. 4551, 1978.

Comments:

QA/QC for Samples 54037 - 54043, 54049, 54050 and 54073.



Chloride

Client:	ConocoPhillips	Project #:	96052-1706
Sample ID:	Background	Date Reported:	05-10-10
Lab ID#:	54040	Date Sampled:	05-05-10
Sample Matrix:	Soil '	Date Received:	05-05-10
Preservative:	Cool	Date Analyzed:	05-07-10
Condition:	Intact	Chain of Custody:	9254

Parameter

Concentration (mg/Kg)

Total Chloride

20

Reference:

U.S.E.P.A., 4500B, "Methods for Chemical Analysis of Water and Wastes", 1983.

Standard Methods For The Examination of Water And Waste Water", 18th ed., 1992.

Comments:

S.J. 30-5 #97M



Chloride

Client:	ConocoPhillips	Project #:	96052-1706
Sample ID:	Reserve Pit	Date Reported:	05-10-10
Lab ID#:	54041	Date Sampled:	05-05-10
Sample Matrix:	Soil `	Date Received:	05-05-10
Preservative:	Cool	Date Analyzed:	05-07-10
Condition:	Intact	Chain of Custody:	9254

Parameter	Concentration (mg/Kg)	

Total Chloride

150

Reference:

U.S.E.P.A., 4500B, "Methods for Chemical Analysis of Water and Wastes", 1983. Standard Methods For The Examination of Water And Waste Water", 18th ed., 1992.

Comments:

S.J. 30-5 #97M

Analyst Analyst

Mustu my Joeten Review

Submit To Appropi	riate District (Office				State of Ne					1			rm C-105		
District I 1625 N. French Dr.	, Hobbs, NM	88240		Ene	ergy, l	Minerals an	d Na	tural Re	sources	ļ	July 1 1. WELL API NO.			uly 17, 2008		
District II 1301 W. Grand Av					0''	1.0	41	D			30-039-30708					
District III 1000 Rio Brazos R						l Conserva 20 South S				ĺ	2. Type of Lease					
District IV						Santa Fe, I			/1.	ŀ	3. State Oil &		Ease No	<u> </u>	FED/INDI	AN
1220 S. St. Francis	Dr., Santa Fe	, NM 8/303				Sama PC, 1	NIVI (37303			SF-078740	043 1				
		ETION	OR F	RECC	MPL	ETION RE	POF	RT AND	LOG							
4. Reason for fill	ing:										5. Lease Name San Juan 30			nent N	lame	
COMPLET	ION REPO	ORT (Fill in	boxes #	#1 throu	gh #31	for State and Fe	e wells	only)		ļ	6. Well Number					
C-144 CLOS #33; attach this a	nd the plat t									or	97M					
7. Type of Comp		WORKOV	ER 🗆	DEEPE	ENING	□PLUGBAC	кΠ	DIFFERE	NT RESERV	OIR	R □ OTHER					
8. Name of Opera	ator	·									9. OGRID					
ConocoPhilli 10. Address of O		any								_	217817	or Wil	dcat			
PO Box 4298, Fa		NM 87499														ľ
12.Location	Unit Ltr	Section		Towns	hip	Range	Lot		Feet from the	he	N/S Line	Feet	from the	E/W	Line	County
Surface:																
BH:																
13. Date Spudded	1 14. Dat	e T.D. Read	ched	15. E		Released		16.	Date Comple	eted	(Ready to Produ	ice)		'. Eleva Γ, GR,		and RKB,
18. Total Measur	ed Depth o	f Well		19. F	Plug Bac	ck Measured De	pth	20.	Was Directi	iona	l Survey Made?					her Logs Run
22. Producing Int	erval(s), of	this compl	etion - T	Γop, Bot	tom, Na	ame		<u> </u>				. <u></u> I				
23.							OR			ing	gs set in we					
CASING SI	ZE	WEIGH	T LB./F	·T.		DEPTH SET		НС	LE SIZE		CEMENTING	3 REC	ORD	<u>A</u>	MOUNT	PULLED
											 					
24.					LINI	ER RECORD				25.	TI	IRIN	G RECO	ORD		
SIZE	TOP		BOT	TOM		SACKS CEM	IENT	SCREE	1	SIZ			PTH SET		PACKI	ER SET
			+-									-			 	
26. Perforation	record (int	erval, size,	and nun	nber)				27. AC	ID, SHOT,	FR	ACTURE, CEN	L MEN'	T, SQUE	EEZE,	ETC.	
									INTERVAL		AMOUNT A					
									 :							
								*								
28.							PRO	DDUC'	TION							
Date First Produc	ction	1	Producti	ion Meti	hod <i>(Fla</i>	owing, gas lift, p	numpin	g - Size an	d type pump)	'	Well Status	(Prod.	or Shut-	in)		
Date of Test	Hours	l'ested	Cho	ke Size		Prod'n For Test Period		Oil - Bb		Gas - MCF Water - Bbl.			Gas - C	oil Ratio		
Flow Tubing Press.	Casing	Pressure		culated 2	24-	Oil - Bbl.		Gas	- MCF	 	Water - Bbl. Oil Gravity - API - (Corn		r.)			
29. Disposition o	[f Gas (Sold	, used for fi	uel, vent	ed, etc.)	,	<u> </u>						30. To	est Witne	ssed B	<u>y</u>	
31. List Attachme	•															
32. If a temporar	y pit was us	sed at the w	ell, attac	ch a plat	with th	e location of the	tempo	orary pit.								
33. If an on-site l	· ·						-	- •								<u></u>
		Latitud	e 36.78	888°N	Lons	gitude 107.3873	31°W	NAD □1	927 × 1983							
I hereby certi	fy that the		_/		Prir	nted	_		•		-			_		r
Signature _	-pt		afor	/		ne Crystal T	аюу	a 11116	. SIAIT K	egu	natory rech	L	Date: /	26	H	
E-mail Addre	ss crysta	ı.tafoya(<i>c</i>	<i>y</i> conoc	cophili	ips.co	<u>m</u>										

ConocoPhillips

Plt Closure Form:		
Date: 6/22/10		
Well Name: SJ 30-S	#1974.	
Footages:		Unit Letter:
Section: 29 , T- 30 -	N, R-5W, County: <u>A:o</u>	AmbaState: NM
Contractor Closing Pit:	Ace Services	· .
Construction inspector:	S.M. Glasson	Date: 6/22/10
Inspector Signature:	<u>(1)2</u>	
	// .	

Tafoya, Crystal

From:

Payne, Wendy F

Sent:

Thursday, May 27, 2010 8:48 AM

To:

(Brandon.Powell@state.nm.us); 'brook@crossfire-llc.com'; GRP:SJBU Regulatory; 'Isaiah Lee'; 'tevans48@msn.com'; (bko@digii.net); Mark Kelly; Robert Switzer; Sherrie Landon; Bassing, Kendal R.; Chavez, Virgil E; Elmer Perry; Faver Norman; Fred Martinez; Jared Chavez; Lowe, Terry; Payne, Wendy F; Silverman, Jason M; Spearman, Bobby E; 'Steve McGlasson'; Tally, Ethel; Becker, Joey W; Bowker, Terry D; Gordon Chenault; GRP:SJBU Production Leads; Hockett, Christy R; Johnson, Kirk L; Bassing, Kendal R.; Kennedy, Jim R; Lopez, Richard A; O'Nan, Mike J.; Peace, James T; Pierce, Richard M; Poulson, Mark E; Smith, Randall O; Spearman, Bobby E; Stamets, Steve A; Thacker, LARRY; Work, Jim A; Blair, Maxwell O; Blakley, Mac; Clark, Joni E; Farrell, Juanita R; Gillette, Steven L (Gray Surface Specialties and Consulting, Ltd.); Greer, David A; Hines, Derek J (Finney Land Co.);

Maxwell, Mary Alice; McWilliams, Peggy L; Seabolt, Elmo F; Stallsmith, Mark R

Cc:

'acedragline@yahoo.com'

Subject:

Reclamation Notice: San Juan 30-5 Unit 97M

Importance:

High

Attachments:

San Juan 30-5 Unit 97M.pdf

Ace Services will move a tractor to the **San Juan 30-5 Unit 97M** to start the reclamation process on Thursday, June 3rd, 2010. Please contact Steve McGlasson (330-4183) if you have questions or need further assistance. Driving directions are attached.



San Juan 30-5 Unit 97M.pdf (36...

ConocoPhillips Well- Network #: 10255300 - D250 (reclamation) & D260 (pit closure)

Rio Arriba County, NM

SAN JUAN 30-5 UNIT 97M-BLM surface / BLM minerals

Twin: San Juan 30-5 Unit 114

690' FNL, 665' FWL

SEC. 29, T30N, R05W

Unit Letter 'D'

Lease #: USA SF-078740

Latitude: 36° 47 min 20.33160 sec N (NAD 83)

Longitude: 107° 23 min 14.68320 sec W (NAD83)

Total Acres Disturbed: 3.258 acres

Access Road: n/a


API #: 30-039-30708

Wendy Payne
ConocoPhillips-SJBU
505-326-9533
Wendy.F.Payne@conocophillips.com

ConocoPhillips

Reclamation Form:
Date: 9/20/10
Well Name: <u>SJ30-5#97M</u>
Footages: 610 FNL 665 FWL Unit Letter: D
Section: <u>29</u> , T- <u>30</u> -N, R- <u>5</u> -W, County: <u>Rio Arib</u> State: <u>M</u>
Reclamation Contractor:
Reclamation Date: 6/10
Reclamation Date: 6/10 Road Completion Date: 9/15/10
Seeding Date: $\frac{9/15/10}{}$
**PIT MARKER STATUS (When Required): Picture of Marker set needed
MARKER PLACED: 9/16/10 (DATE)
LATATUDE: 36.78888 NAO83
LONGITUDE: 107, 3873/
Pit Manifold removed Othe unknown (DATE)
Construction Inspector: SMEGIasson Date: \(\frac{120}{10} \)
Inspector Signature:
\mathcal{O}

BLM









	WELL NAME: San Juan 30-5 Unit 97M	OPEN P	PIT INSPE	ECTION F	FORM				ConocoPhillips	SQ
	INSPE	Scott Smith	Scott Smith	Scott Smith	Scott Smith	Scott Smith	Scott Smith	Scott Smith	Scott Smith	Scott Smith
	DATE	07/08/09 Week 1	07/10/09 Week 2	07/17/09 Week 3	07/24/09 Week 4	08/02/09 Week 5	08/07/09 Week 6	08/14/09 Week 7	08/24/09 Week 8	08/28/09 Week 9
	PIT STATUS	Drilled Completed	✓ Drilled ☐ Completed ☐ Clean-Up	✓ Drilled ☐ Completed ☐ Clean-Up	✓ Drilled ☐ Completed ☐ Clean-Up	S Drilled Completed Clean-Up	✓ Drilled	U Drilled Completed Clean-Up	O Drilled Completed Clean-Up	✓ Drilled ☐ Completed ☐ Clean-Up
NOI	Is the location marked with the proper flagging? (Const. Zone, poles, pipelines, etc.)	☐ Yes ☐ No	☑ Yes ☐ No	✓ Yes No	✓ Yes 🗆 No	✓ Yes □ No	✓ Yes 🗆 No	✓ Yes 🗆 No	□ Yes □ No	✓ Yes No
10CA	Is the temporary well sign on location and visible from access road?	☐ Yes ☐ No	✓ Yes 🗌 No	✓ Yes 🗆 No	✓ Yes 🗀 No	✓ Yes 🗆 No	☑ Yes ☐ No	☑ Yes ☐ No	□.Yes □ No	☑ Yes ☐ No
9	Is the access road in good driving condition? (deep ruts, bladed)	☐ Yes ☐ No	✓ Yes 🗌 No	☑ Yes ☐ No	✓ Yes 🗆 No	✓ Yes □ No	✓ Yes 🗆 No	✓ Yes 🗌 No	☐ Yes ☐ No	✓ Yes □ No
	Are the culverts free from debris or any object preventing flow?	☐ Yes ☐ No	✓ Yes ☐ No	✓ Yes 🗆 No	✓ Yes 🗆 No	✓ Yes 🗌 No	✓ Yes 🗌 No	✓ Yes 🗌 No	☐ Yes ☐ No	✓ Yes ☐ No
	is the top of the location bladed and in good operating condition?	☐ Yes ☐ No	✓ Yes ☐ No	☑ Yes ☐ No	✓ Yes 🗌 No	✓ Yes 🗌 No	✓ Yes 🗍 No	✓ Yes 🗌 No	☐ Yes ☐ No	✓ Yes 🗌 No
NCE	Is the fence stock-proof? (fences light, barbed wire, fence clips in place?	☐ Yes ☐ No	✓ Yes □ No	✓ Yes 🗆 No	✓ Yes 🗌 No	✓ Yes 🗌 No	✓ Yes 🗌 No	✓ Yes 🗌 No	☐ Yes ☐ No	✓ Yes ☐ No
AIJ4N	Is the pit liner in good operating condition? (no tears, up-rooting corners, etc.)	☐ Yes ☐ No	✓ Yes ☐ No	✓ Yes 🗆 No	✓ Yes 🗌 No	✓ Yes 🗌 No	✓ Yes 🗌 No	✓ Yes 🗌 No	☐ Yes ☐ No	✓ Yes ☐ No
r cov	Is the the location free from trash, oil stains and other materials? (cables, pipe threads, etc.)	☐ Yes ☐ No	✓ Yes 🗌 No	✓ Yes, ☐ No	✓ Yes 🗌 No	✓ Yes 🗌 No	✓ Yes 🗌 No	✓ Yes 🗌 No	☐ Yes ☐ No	✓ Yes ☐ No
ATN3/	Does the pit contain two feet of free board? (check the water levels)	☐ Yes ☐ No	✓ Yes ☐ No	✓ Yes 🗌 No	✓ Yes 🗌 No	✓ Yes ☐ No	✓ Yes 🗌 No	✓ Yes 🗌 No	☐ Yes ☐ No	✓ Yes ☐ No
МИОЯ	Is there any standing water on the blow pit?	☐ Yes ☐ No	✓ Yes □ No	✓ Yes 🗆 No	✓ Yes 🗌 No	✓ Yes 🗌 No	✓ Yes 🗌 No	✓ Yes 🗌 No	☐ Yes ☐ No	✓ Yes ☐ No
ENAII	Are the pits free of trash and oil?	☐ Yes ☐ No	✓ Yes 🗌 No	✓ Yes ☐ No	✓ Yes 🗌 No	✓ Yes ☐ No	✓ Yes 🗌 No	✓ Yes 🗌 No	☐ Yes ☐ No	✓ Yes ☐ No
	Are there diversion ditches around the pits for natural drainage?	Ves No	□ Yes ☑ No	Nes ☑ No	✓ Yes 🗌 No	√ Yes No	✓ Yes 🗆 No	✓ Yes 🗌 No	☐ Yes ☐ No	✓ Yes ☐ No
A	Is there a Manifold on location?	☐ Yes ☐ No	✓ Yes 🗌 No	✓ Yes 🗌 No	✓ Yes 🗆 No	√ Yes □ No	✓ Yes 🗌 No	✓ Yes 🗌 No	☐ Yes ☐ No	✓ Yes ☐ No
	Is the Manifold free of leaks? Are the hoses in good condition?	☐ Yes ☐ No	✓ Yes 🗌 No	☑ Yes ☐ No	☑ Yes ☐ No	∠ Yes □ No	∠ Yes □ No	✓ Yes 🗆 No	T yes No	✓ Yes 🗌 No
ОС	Was the OCD cor	☐ Yes ☐ No	☐ Yes ☑ No	☐ Yes ☑ No	☐ Yes ☑ No	☐ Yes ☑ No	☐ Yes ☑ No		☐ Yes ☐ No	☐ Yes ☑ No
	PICTURE TAKEN	☐ Yes ☐ No	✓ Yes 🗌 No	☑ Yes		✓ Yes 🗆 No	✓ Yes 🗌 No	☑ Yes ☐ No	☐ Yes ☐ No	✓ Yes 🗌 No
	COMMENTS	Rig on Location	Fence & liner in Fgood condition: good condition: good good good good good good good goo	Fence & liner in good condition; no diversion ditch @ pit	Fence & liner in good condition	, liner in ondition; g @ anchor E side of pit	Fence & liner in good condition	Fence & liner in good condition	Wireline crew on location	Fence & liner in good condition

SPECTOR Scort Smith Scott Smith Sco		WELL NAME:									
National Control National Co		San Juan 30-5 Unit 7/M							111-0 11-0	4000	qims itoos
These required to pic stands of the pic stands o		INSPECTOR	Scott Smith	Scott Smith	Scott Smith	Scott Smith 10/19/09	11/04/09	11/06/09	11/13/09	11/20/09	12/09/09
Springer County Long			Week 10	Week 11	Week 12	Week 13	Week 14	Week 15	Week 16	Week 17	Week 18
State because with the propertionaging? Symple Symp		PIT STATUS	✓ Drilled Completed	✓ Drilled ✓ Completed	☐ Drilled☐ Completed☐ Clean Ib	✓ Drilled ☐ Completed	✓ Drilled Completed	✓ Drilled ☐ Completed ☐ Clean-Up	✓ Drilled ☐ Completed ☐ Clean-Up	✓ Drilled ✓ Completed ☐ Clean-Up	✓ Drilled ✓ Completed ☐ Clean-Up
Count. Come, Solice pipelines, set.) Cross	NC	Is the location marked with the proper flagging?	✓ Yes No			✓ Yes □ No	✓ Yes □ No	✓ Yes No	Yes No	✓ Yes No	✓ Yes □ No
It the recent of the board of t	ΙΤΑ	(Const. Zone, poles, pipelines, etc.)									
State and the good diving condition? Cyes No C	100	Is the temporary well sign on location and visible from access road?	☑ Yes ☐ No	✓ Yes 🗌 No	✓ Yes 🗌 No	✓ Yes 🗌 No	✓ Yes 🗀 No	✓ Yes 🗌 No	☐ Yes ☐ No	✓ Yes 🔲 No	✓ Yes □ No
Are the culvert free from debtis or any object 2 yes 100 2 yes 1		Is the access road in good driving condition? (deep ruts, bladed)	✓ Yes 🗌 No	✓ Yes 🗌 No			✓ Yes 🗌 No	☑ Yes ☐ No	□ Yes □ No	✓ Yes 🗌 No	✓ Yes □ No
State From Carlot Didded and in good operating condition? Sing Time Sing	- WF V7	Are the culverts free from debris or any object preventing flow?	✓ Yes 🗌 No	✓ Yes No		✓ Yes □ No	✓ Yes 🗌 No	✓ Yes 🗆 No		✓ Yes □ No	✓ Yes 🗌 No
Is the fence citos in place? Is the pliner in good operating condition? (no learned in the pliner in good operating condition? (no learned in the pliner in good operating condition? (no learned in the pliner in good operating condition? (no learned in good operating condition? (no learned in pool operating condition? (no learned condition? (no lea		is the top of the location bladed and in good operating condition?	✓ Yes ☐ No	✓ Yes □ No		✓ Yes ☐ No	✓ Yes 🗌 No	☑ Yes ☐ No	☐ Yes ☐ No	✓ Yes No	✓ Yes 🗌 No
Is the pit liner in good operating condition? (no 2 yes 10 2 yes	NCE	Is the fence stock-proof? (fences tight, barbed wire, fence clips in place?	✓ Yes □ No			✓ Yes ☐ No	✓ Yes 🗆 No			☐ Yes < No	√ Yes □ No
Street the location free from frash, oil stains and other materials? (cables, pipe threads, etc.) Cyes No	AIJ9N	Is the pit liner in good operating condition? (no tears, up-rooting corners, etc.)	✓ Yes □ No	✓ Yes 🗆 No		✓ Yes ☐ No	✓ Yes 🗌 No	☑ Yes ☐ No	☐ Yes ☐ No	✓ Yes No	✓ Yes ☐ No
Does the pit contain two feet of free board? (Check	r cov	Is the the location free from trash, oil stains and other materials? (cables, pipe threads, etc.)	✓ Yes No	✓ Yes 🗌 No		✓ Yes □ No	✓ Yes 🗌 No		☐ Yes ☐ No	✓ Yes □ No	√ Yes □ No
Is there any standing water on the blow pit? Are the pits free of trash and oil? Are the pits free of trash and oil. Ar	ATN3/	Does the pit contain two feet of free board? (check the water levels)	✓ Yes ☐ No		✓ Yes 🗌 No	✓ Yes 🗌 No	✓ Yes No		□ Yes □ No	√ Yes □ No	✓ Yes ☐ No
Are the pits free of trash and oil? Are there diversion ditches around the pits for a care and oils are there diversion ditches around the pits for a care and an items of the care and an items of	MNOS	Is there any standing water on the blow pit?	✓ Yes ☐ No	✓ Yes □ No		✓ Yes ☐ No	✓ Yes ☐ No		☐ Yes ☐ No	✓ Yes No	✓ Yes 🗌 No
Are there diversion ditches around the pits for a control of the drainage? Is there a Manifold on location? Is there a Manifold free of leaks? Are the hoses in a condition? Is the Manifold free of leaks? Are the hoses in a condition? Is the Manifold free of leaks? Are the hoses in a condition? In the Manifold free of leaks? Are the hoses in a condition? In the Manifold free of leaks? Are the hoses in a condition? In the Manifold free of leaks? Are the hoses in a condition? In the Manifold free of leaks? Are the hoses in a condition? In the Manifold free of leaks? Are the hoses in a condition? In the Manifold free of leaks? Are the hoses in a condition? In the Manifold free of leaks? Are the hoses in a condition? In the Manifold free of leaks? Are the hoses in a condition? In the Manifold free of leaks? Are the hoses in a condition? In the Manifold free of leaks? Are the hoses in a condition? In the Manifold free of leaks? Are the hoses in a condition? In the Manifold free of leaks? Are the hoses in a condition and a condition and a condition and a condition. In the Manifold free of leaks? Are the hoses in a condition and a conditio	EΝΛΙ	Are the pits free of trash and oil?				✓ Yes	✓ Yes 🗆 No		□ Yes □ No	√ Yes □ No	✓ Yes 🗆 No
Is there a Manifold on location? Is the Manifold free of leaks? Are the hoses in Signature and an interval of the Manifold free of leaks? Are the hoses in Signature and an interval of the Manifold free of leaks? Are the hoses in Signature and an interval of the Manifold free of leaks? Are the hoses in Signature and an interval of the Manifold free of leaks? Are the hoses in Signature and an interval of the Manifold free of leaks? Are the hoses in Signature and an interval of the Manifold free of leaks? Are the Manifold free of leaks? A	200 , 10,00 o a securito 200	Are there diversion ditches around the pits for natural drainage?	✓ Yes ☐ No	✓ Yes		✓ Yes 🗆 No	✓ Yes 🗌 No	χes	□ Yes □ No	☑ Yes ☐ No	✓ Yes No
Is the Manifold free of leaks? Are the hoses in good condition? ☑ Yes ☐ No ☐ Yes ☐ No<		Is there a Manifold on location?	✓ Yes ☐ No	✓ Yes		✓ Yes 🗌 No	✓ Yes 🗌 No	, es	☐ Yes ☐ No	✓ Yes 🗌 No	✓ Yes 🗌 No
□ Was the OCD contacted? □ Yes ⊆ No □ Yes ⊆ No □ Yes ⊆ No □ Yes ⊆ No PICTURE TAKEN □ Yes □ No		Is the Manifold free of leaks? Are the hoses in good condition?	✓ Yes 🗌 No		_	✓ Yes 🗌 No	☑ Yes ☐ No	☑ Yes ☐ No	☐ Yes ☐ No	✓ Yes 🗆 No	✓ Yes 🗆 No
PICTURE TAKEN Street No	a a	Was the OCD contacted?	☐ Yes ☑ No			☐ Yes ☑ No	☐ Yes ☑ No	☐ Yes ☑ No	☐ Yes ☐ No	☐ Yes ☑ No	☐ Yes ☑ No
Fence & liner in	7.6	PICTURE TAKEN	☑ Yes ☐ No	on 🗌	i——i	☑ Yes ☐ No	☑ Yes ☐ No	✓ Yes 🗆 No		√ Yes 🗆 No	✓ Yes 🗌 No
COMMENTS Fence & liner in good Fence & liner in good Fence & liner in good condition Fe		COMMENTS	Fence & liner in good condition	Fence & liner in good condition		Fence & liner in good condition; called Nobles to haul water in pit to prep for winter	Liner in good condition; fence loose	Fence & liner in good condifion	Rig on location	Liner in good condition; fence loose, clips M	Fence & liner in good condilion

	WELL NAME: San Juan 30-5 Unit 97M									
	띯	S. McGlasson	S. McGlasson	S. McGlasson	S. McGlasson	Freddie Mtz	Freddie Mtz	Freddie Mtz	S. McGlasson	S. McGlasson
	DATE **Please request for pil extention after 26 weeks	02/24/10 Week 19	03/01/10 Week 20	03/18/10 Week 21	03/29/10 Week 22	04/21/10 Week 23	05/03/10 Week 24	05/05/10 Week 25	06/22/10 *Week 26*	06/10/11 Week 27
	PIT STATUS	S Drilled C Completed	✓ Drilled ✓ Completed	✓ Drilled ✓ Completed	✓ Drilled ✓ Completed	Drilled Completed	Drilled Completed			
N	Is the location marked with the proper flagging?									
ΣΙΤ∠			ON 100	ON Sat S	ON Sat I	ON C Sai C	ON Cal	ON The same		ON] (5)
/201	Is the temporary well sign on location and visible from access road?	✓ Yes 🗌 No	✓ Yes 🗌 No	☑ Yes ☐ No	☑ Yes ☐ No	✓ Yes 🗌 No	☑ Yes ☐ No	∠ Yes 🗌 No	☐ Yes ☐ No	☐ Yes ☐ No
	<u> </u>	✓ Yes 🗆 No	✓ Yes 🗆 No	✓ Yes 🗆 No	☐ Yes ☑ No	✓ Yes ☐ No	ON 🗌 SeX 🔼	✓ Yes 🗆 No	Nes □ No	☐ Yes ☐ No
	Are the culverts free from debris or any object preventing flow?	✓ Yes 🗌 No	✓ Yes ☐ No	✓ Yes 🗆 No	✓ Yes ☐ No	✓ Yes ☐ No	✓ Yes 🗆 No	✓ Yes □ No	□ Yes □ No	☐ Yes ☐ No
	Is the top of the location bladed and in good operating condition?	✓ Yes No	✓ Yes ☐ No	✓ Yes 🗌 No	☐ Yes ☑ No	✓ Yes ☐ No	☑ Yes ☐ No	✓ Yes □ No	☐ Yes ☐ No	□ Yes □ No
NCE	<u>' </u>	✓ Yes 🗌 No	✓ Yes ☐ No	✓ Yes 🗆 No	✓ Yes ☐ No	☐ Yes ☑ No	✓ Yes ✓ No	✓ Yes □ No	□ Yes □ No	☐ Yes ☐ No
AIJ9M	Is the pit liner in good operating condition? (no tears, up-rooting corners, etc.)	✓ Yes 🗌 No	✓ Yes 🗌 No	✓ Yes 🗆 No	☑ Yes ☐ No	✓ Yes ☐ No	✓ Yes 🗆 No	✓ Yes □ No	□ Yes □ No	☐ Yes ☐ No
(CO	Is the the location free from trash, oil stains and other materials? (cables, pipe threads, etc.)	✓ Yes 🗌 No	✓ Yes 🗆 No	✓ Yes 🗌 No	ON L SAK	✓ Yes 🗆 No	✓ Yes 🗆 No	✓ Yes ☐ No	ON 🗌 Yes 📋	□ Yes □ No
ATN∃	Does the pit contain two feet of free board? (check the water levels)	✓ Yes No	✓ Yes ☐ No	☑ Yes ☐ No	✓ Yes 🗌 No	✓ Yes 🗌 No	✓ Yes 🗌 No	✓ Yes 🗌 No	☐ Yes ☐ No	☐ Yes ☐ No
ВОИЛ	Is there any standing water on the blow pit?	✓ Yes 🗌 No	✓ Yes 🗆 No	✓ Yes 🗆 No	✓ Yes ☐ No	☑ Yes ☐ No	☑ Yes ☐ No	✓ Yes 🗌 No	☐ Yes ☐ No	☐ Yes ☐ No
ΕΝΛΙ	Are the pits free of trash and oil?	✓ Yes No	✓ Yes 🗆 No	✓ Yes 🗌 No	✓ Yes ☐ No	✓ Yes 🗌 No	√ Yes No	☑ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No
	Are there diversion ditches around the pits for natural drainage?	✓ Yes 🗌 No	✓ Yes 🗆 No	☑ Yes ☐ No	✓ Yes ☐ No	✓ Yes ☐ No	☑ Yes ☐ No	✓ Yes 🗌 No	☐ Yes ☐ No	☐ Yes ☐ No
THE SEC 1 SAME OF 18	Is there a Manifold on location?	☐ Yes ✓ No	☐ Yes ☑ No	☐ Yes ☑ No	☐ Yes ☑ No	✓ Yes 🗌 No	□ Yes □ No	✓ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No
	Is the Manifold free of leaks? Are the hoses in good condition?	☐ Yes ☑ No	☐ Yes ☑ No	☐ Yes ☑ No	Tres J No	✓ Yes 🗌 No	☐ Yes ☐ No	✓ Yes 🗌 No	☐ Yes ☐ No	☐ Yes ☐ No
0 OC	Was the OCD contacted?	☐ Yes ☑ No	☐ Yes ☑ No	☐ Yes ☑ No	☐ Yes ☐ No	☐ Yes ☐ No				
ration of the state of the stat	PICTURE TAKEN	☑ Yes ☐ No	✓ Yes 🗌 No	☑ Yes ☐ No	☑ Yes ☐ No	☐ Yes ☑ No	☐ Yes ☑ No	☐ Yes ☑ No	☐ Yes ☐ No	☐ Yes ☐ No
	COMMENTS					Contact Flint to lix fence	st Flint to e	Tested pit.	Pit Closed	Location Reclaimed & Pit Marker Placed