



NEW MEXICO ENERGY, MINERALS and
NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 2-14-2011 Operator Burlington Res. API # 30-0 45-35126

Property Name Mal Vista SWD Well # 1 Location: Unit N Sec 2 Twn 29 Rge 11

Land Type:

State
Federal
Private
Indian

Well Type:

Water Injection
Salt Water Disposal /
Gas Injection
Producing Oil/Gas
Pressure observation

Temporarily Abandoned Well (Y/N): TA Expires:

Casing Pres. 0 Tbg. SI Pres. Max. Inj. Pres.
Bradenhead Pres. 0 Tbg. Inj. Pres.
Tubing Pres. 0
Int. Casing Pres. 0

RCVD FEB 14'11

OIL CONS. DIV.

DIST. 3

Pressured annulus up to 419 psi. for 30 mins. Test passed/failed

REMARKS:

Packer set at 3602

top plug at 3662

BT test performed & passed

fill check will need to be performed with witness.


By [Signature]
(Operator Representative)

Witness [Signature]
(NMOCD)

SWD SUPERVISOR
(Position)

Revised 02-11-02

PRINTED IN U.S.A.



SF

SOUTHERN FLOW
COMPANIES, INC.

BURLINGTON
METER NUMBER

MAR VISTA SWD #1
TIME PUT ON

REALISS M
DATE PUT ON

2-14-2011

B 0-1000-12-2HR

SIGNED

[Signature]

TUBE & ORIF. SIZE

TIME TAKEN OFF

DATE TAKEN OFF

M

20