



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT


(submit 1 copy to above address)

Date of Test 10/26/10 Operator Blackhills Gas Res. API #30-0 39-25941
Property Name Jicarilla ^{5.5} 459-20 Well No. 12 Location: Unit 0 Section 20 Township 30N Range 3W
Well Status (Shut-In or Producing) Initial PSI: Tubing 37 Intermediate N/A Casing 32 Bradenhead 12

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead			Int	Csg
	BH	Int	Csg		
TIME					
5 min	<u>3</u>		<u>32</u>		
10 min	<u>4</u>		<u>32</u>		
15 min	<u>4</u>		<u>32</u>		
20 min	<u>4</u>		<u>32</u>		
25 min	<u>4</u>		<u>32</u>		
30 min	<u>4</u>		<u>32</u>		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	☒
Nothing	
Gas	☒
Gas & Water	
Water	



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH ✓ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 3

INTERMEDIATE N/A

REMARKS:

no water, but had 12th pressure on bradenhead.
Blew down to nothing in a few seconds.

By Kirt D. Vicenti
Lease operator
(Position)

Witness _____

E-mail address Kirt.Vicenti@bhep.com