



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 8/9/10 Operator Energizer Resources API #30-039-30546 ✓
Property Name San Juan 32-5 Unit Unit Com Well No. 115 Location: Unit P Section 22 Township 32N Range 6W ✓
Well Status (Shut-In or Producing) Producing Tubing 120 Intermediate N/A Casing 365 Bradenhead 125

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING		
5 minutes	<u>0</u>	<u>N/A</u>	<u>365</u>	Steady Flow <u>✓</u>	
10 minutes	<u>0</u>		<u>365</u>	Surges	
15 minutes	<u>0</u>		<u>365</u>	Down to Nothing	
20 minutes	<u>0</u>		<u>365</u>	Nothing	
25 minutes	<u>0</u>		<u>365</u>	Gas <u>✓</u>	<u>N/A</u>
30 minutes	<u>0</u>		<u>365</u>	Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 75 INTERMEDIATE N/A

REMARKS:

Braden had slight blow while open to atmosphere

By Alan Kirk
Senior Lease Operator
(Position)

Witness _____

E-mail address _____

