1625 N. French Dr., Hobbs, NM 88240

1301 W. Grand Ave., Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

State of New Mexico Energy Minerals and Natural Resources

Department Oil Conservation Division 1220 South St. Francis Dr.

Santa Fe, NM 87505

Form C-144 July 21, 2008

For temporary pits, closed-loop sytems, and below-grade tanks, submit to the appropriate NMOCD District Office.

For permanent pits and exceptions submit to the Santa Fe Environmental Bureau office and provide a copy to the appropriate NMOCD District Office.

District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 Pit, Closed-Loop System, Below-Grade Tank, or Proposed Alternative Method Permit or Closure Plan Application 6830 Type of action: Permit of a pit, closed-loop system, below-grade tank, or proposed alternative method X Closure of a pit, closed-loop system, below-grade tank, or proposed alternative method Modification to an existing permit Closure plan only submitted for an existing permitted or non-permitted pit, closed-loop system, below-grade tank, or proposed alternative method Instructions: Please submit one application (Form C-144) per individual pit, closed-loop system, below-grade tank or alternative request Please be advised that approval of this request does not relieve the operator of liability should operations result in pollution of surface water, ground water or the environment. Nor does approval relieve the operator of its responsibility to comply with any other applicable governmental authority's rules, regulations or ordinances. Operator: ConocoPhillips Company OGRID#: 217817 Address: P.O. Box 4289, Farmington, NM 87499 Facility or well name: SAN JUAN 30-5 UNIT 81N API Number: 30-039-30765 OCD Permit Number: U/L or Qtr/Qtr: F(SE/NW) Section: 27 Township: 30N Range: County: Rio Arriba Center of Proposed Design: Latitude: °W NAD: [36,786742 ٥N Longitude: 107.348231 1927 X 1983 X Private Tribal Trust or Indian Allotment Surface Owner: Federal X Pit: Subsection F or G of 19.15.17.11 NMAC X Drilling Workover Temporary: Permanent Emergency Cavitation P&A X LLDPE HDPE PVC Other X Lined Unlined Liner type: Thickness 20 mil X String-Reinforced X Welded X Factory Volume: 7700 bbl Dimensions L 120' x W 55' Subsection H of 19.15.17.11 NMAC Closed-loop System: Drilling a new well Workover or Drilling (Applies to activities which require prior approval of a permit or Type of Operation: P&A notice of intent) Above Ground Steel Tanks Haul-off Bins Other LLDPE HDPE Lined Unlined Liner type: Thickness mil Welded [Liner Seams: Factory Other Below-grade tank: Subsection I of 19.15.17.11 NMAC Volume: hbl Type of fluid: Tank Construction material: Secondary containment with leak detection Visible sidewalls, liner, 6-inch lift and automatic overflow shut-off Visible sidewalls only Other Visible sidewalls and liner HDPE Liner Type: **iPVC** Other

Submittal of an exception request is required. Exceptions must be submitted to the Santa Fe Environmental Bureau office for consideration of approval.

Fencing: Subsection D of 19.15.17.11 NMAC (Applies to permanent pit, temporary pits, and below-grade tanks) Chain link, six feet in height, two strands of barbed wire at top (Required if located within 1000 feet of a permanent residence, school, hospital, institt Four foot height, four strands of barbed wire evenly spaced between one and four feet Alternate. Please specify	ution or church)
Netting: Subsection E of 19.15.17.11 NMAC (Applies to permanent pits and permanent open top tanks) Screen Netting Other Monthly inspections (If netting or screening is not physically feasible)		
Signs: Subsection C of 19.15.17.11 NMAC 12" X 24", 2" lettering, providing Operator's name, site location, and emergency telephone numbers X Signed in compliance with 19.15.3.103 NMAC		
Administrative Approvals and Exceptions: Justifications and/or demonstrations of equivalency are required. Please refer to 19.15.17 NMAC for guidance. Please check a box if one or more of the following is requested, if not leave blank: Administrative approval(s): Requests must be submitted to the appropriate division district of the Santa Fe Environmental Bureau office for consideration (Fencing/BGT Liner) Exception(s): Requests must be submitted to the Santa Fe Environmental Bureau office for consideration of approval.	deration of app	roval.
Siting Criteria (regarding permitting) 19.15.17.10 NMAC Instructions: The applicant must demonstrate compliance for each siting criteria below in the application. Recommendations of acceptable source material are provided below. Requests regarding changes to certain siting criteria may require administrative approval from the appropriate district office or may be considered an exception which must be submitted to the Santa Fe Environmental Bureau Office for consideration of approval. Applicant must attach justification for request. Please refer to 19.15.17.10 NMAC for guidance. Siting criteria does not apply to drying pads or above grade-tanks associated with a closed-loop system.		
Ground water is less than 50 feet below the bottom of the temporary pit, permanent pit, or below-grade tank. - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	Yes	No
Within 300 feet of a continuously flowing watercourse, or 200 feet of any other watercourse, lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark). - Topographic map; Visual inspection (certification) of the proposed site	Yes	□No
Within 300 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application.	Yes	No
(Applies to temporary, emergency, or cavitation pits and below-grade tanks) - Visual inspection (certification) of the proposed site; Aerial photo; Satellite image	□NA	
Within 1000 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. (Applied to permanent pits) - Visual inspection (certification) of the proposed site; Aerial photo; Satellite image	Yes NA	No
Within 500 horizonal feet of a private, domestic fresh water well or spring that less than five households use for domestic or stock watering purposes, or within 1000 horizontal feet of any other fresh water well or spring, in existence at the time of initial application.	Yes	No
- NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site.		
Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance adopted pursuant to NMSA 1978, Section 3-27-3, as amended - Written confirmation or verification from the municipality; Written approval obtained from the municipality	Yes	∐No
Within 500 feet of a wetland. - US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site	Yes	No
Within the area overlying a subsurface mine Written confirmation or verification or map from the NM EMNRD - Mining and Mineral Division	Yes	No
Within an unstable area. - Engineering measures incorporated into the design; NM Bureau of Geology & Mineral Resources; USGS; NM Geological Society; Topographic map	Yes	No
Within a 100-year floodplain - FEMA map	Yes	No

Temporary Pits, Emergency Pits and Below-grade Tanks Permit Application Attachment Checklist Subsection B of 19.15.17.9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached.
Hydrogeologic Report (Below-grade Tanks) - based upon the requirements of Paragraph (4) of Subsection B of 19.15.17.9 NMAC
Hydrogeologic Data (Temporary and Emergency Pits) - based upon the requirements of Paragraph (2) of Subsection B of 19.15.17.9
Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC
Design Plan - based upon the appropriate requirements of 19.15.17.11 NMAC
Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC
Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of
19.15.17.9 NMAC and 19.15.17.13 NMAC
Previously Approved Design (attach copy of design) APIor Permit
Closed-loop Systems Permit Application Attachment Checklist: Subsection B of 19.15.17.9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached. Geologic and Hydrogeologic Data (only for on-site closure) - based upon the requirements of Paragraph (3) of Subsection B of 19.15.17.9
Siting Criteria Compliance Demonstrations (only for on-site closure) - based upon the appropriate requirements of 19.15.17.10 NMAC
Design Plan - based upon the appropriate requirements of 19.15.17.11 NMAC
Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC
Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19.15.17.9 NMAC and 19.15.17.13 NMAC
Previously Approved Design (attach copy of design) API
Previously Approved Operating and Maintenance Plan API
13
Permanent Pits Permit Application Checklist: Subsection B of 19.15.17.9 NMAC
Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached.
Hydrogeologic Report - based upon the requirements of Paragraph (I) of Subsection B of 19.15.17.9 NMAC
Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC
Climatological Factors Assessment
Certified Engineering Design Plans - based upon the appropriate requirements of 19.15.17.11 NMAC
Dike Protection and Structural Integrity Design: based upon the appropriate requirements of 19.15.17.11 NMAC
Leak Detection Design - based upon the appropriate requirements of 19.15.17.11 NMAC Liner Specifications and Compatibility Assessment - based upon the appropriate requirements of 19.15.17.11 NMAC
Quality Control/Quality Assurance Construction and Installation Plan
Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC
Freeboard and Overtopping Prevention Plan - based upon the appropriate requirements of 19.15.17.11 NMAC
Nuisance or Hazardous Odors, including H2S, Prevention Plan
Emergency Response Plan
Oil Field Waste Stream Characterization
Monitoring and Inspection Plan
Erosion Control Plan
Closure Plan - based upon the appropriate requirements of Subsection C of 19.15.17.9 NMAC and 19.15.17.13 NMAC
Proposed Closure: 19.15.17.13 NMAC
Instructions: Please complete the applicable boxes, Boxes 14 through 18, in regards to the proposed closure plan.
Type: Drilling Workover Emergency Cavitation P&A Permanent Pit Below-grade Tank Closed-loop System Alternative
Proposed Closure Method: Waste Excavation and Removal
Waste Removal (Closed-loop systems only)
On-site Closure Method (only for temporary pits and closed-loop systems)
In-place Burial On-site Trench
Alternative Closure Method (Exceptions must be submitted to the Santa Fe Environmental Bureau for consideration)
Waste Excavation and Removal Closure Plan Checklist (19.15.17.13 NMAC) Instructions: Each of the following items must be attached to the closure plan.
Please indicate, by a check mark in the box, that the documents are attached.
Protocols and Procedures - based upon the appropriate requirements of 19.15.17.13 NMAC
Confirmation Sampling Plan (if applicable) - based upon the appropriate requirements of Subsection F of 19.15.17.13 NMAC Disposal Facility Name and Permit Number (for liquids, drilling fluids and drill cuttings)
Soil Backfill and Cover Design Specifications - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC
Re-vegetation Plan - based upon the appropriate requirements of Subsection I of 19.15.17.13 NMAC
Site Reclamation Plan - based upon the appropriate requirements of Subsection G of 19.15.17.13 NMAC

Form C-144 Oil Conservation Division Page 3 of 5

16 Waste Removal Closure For Closed-loop Systems That Utilize Above Grou	ind Steel Tanks or Haul-off Bins Only:(19.15.17.13.D NMAC)	·
Instructions: Please identify the facility or facilities for the disposal of liquids, a facilities are required.)
Disposal Facility Name:	Disposal Facility Permit #:	
Disposal Facility Name:		
Will any of the proposed closed-loop system operations and associated Yes (If yes, please provide the information No		
Required for impacted areas which will not be used for future service and oper Soil Backfill and Cover Design Specification - based upon the a Re-vegetation Plan - based upon the appropriate requirements of Site Reclamation Plan - based upon the appropriate requirements	appropriate requirements of Subsection H of 19.15.17.13 N Subsection I of 19.15.17.13 NMAC	NMAC
Siting Criteria (Regarding on-site closure methods only: 19.15.17.10 Instructions: Each siting criteria requires a demonstration of compliance in the closure p certain siting criteria may require administrative approval from the appropriate district of office for consideration of approval. Justifications and/or demonstrations of equivalency	lan. Recommendations of acceptable source material are provided belov office or may be considered an exception which must be submitted to the	
Ground water is less than 50 feet below the bottom of the buried waste		Yes No
- NM Office of the State Engineer - iWATERS database search; USGS: D	ata obtained from nearby wells	□N/A
Ground water is between 50 and 100 feet below the bottom of the burie	ed waste	Yes No
- NM Office of the State Engineer - iWATERS database search; USGS; USG	ata obtained from nearby wells	N/A
Ground water is more than 100 feet below the bottom of the buried wa	ste.	Yes No
- NM Office of the State Engineer - iWATERS database search; USGS; USGS; Database search; USGS; USGS	ata obtained from nearby wells	∏N/A
Within 300 feet of a continuously flowing watercourse, or 200 feet of any other (measured from the ordinary high-water mark).	significant watercourse or lakebed, sinkhole, or playa lake	Yes No
- Topographic map; Visual inspection (certification) of the proposed site		
Within 300 feet from a permanent residence, school, hospital, institution, or che - Visual inspection (certification) of the proposed site; Aerial photo; satellit	••	Yes No
Within 500 horizontal feet of a private, domestic fresh water well or spring that purposes, or within 1000 horizontal fee of any other fresh water well or spring, - NM Office of the State Engineer - iWATERS database; Visual inspection	in existence at the time of the initial application. (certification) of the proposed site	Yes No
Within incorporated municipal boundaries or within a defined municipal fresh w pursuant to NMSA 1978, Section 3-27-3, as amended. - Written confirmation or verification from the municipality; Written approximation of the municipality with the section of the se	·	Yes No
Within 500 feet of a wetland - US Fish and Wildlife Wetland Identification map; Topographic map; Vis		Yes No
Within the area overlying a subsurface mine. - Written confirantion or verification or map from the NM EMNRD-Minin	• • • •	Yes No
Within an unstable area Engineering measures incorporated into the design; NM Bureau of Geological Control of the design of the design of Geological Control of the design of the design of Geological Control of the design of the design of Geological Control of the design of the design of Geological Control of the design		Yes No
Topographic map Within a 100-year floodplain FEMA map		Yes No
18 On-Site Closure Plan Checklist: (19.15.17.13 NMAC) Instructions:	Each of the following items must bee attached to the cl	osure plan. Please indicate,
by a check mark in the box, that the documents are attached.		
Siting Criteria Compliance Demonstrations - based upon the ap	• •	
Proof of Surface Owner Notice - based upon the appropriate rec	•	,
Construction/Design Plan of Topporary Pit (for in place by rich	• • • •	
Construction/Design Plan of Temporary Pit (for in place burial Protocols and Procedures - based upon the appropriate requiren		\$ 0f 19.15.17.11 NMAC
Confirmation Sampling Plan (if applicable) - based upon the ap		/AC
Waste Material Sampling Plan - based upon the appropriate req		
Disposal Facility Name and Permit Number (for liquids, drilling		ds cannot be achieved)
Soil Cover Design - based upon the appropriate requirements of	-	
Re-vegetation Plan - based upon the appropriate requirements of		•
Cita Paglamatian Plan, based upon the appropriate requirement	to of Subscation C of 10:15 17 12 NMAC	;

Form C-144 Oil Conservation Division Page 4 of 5

19 Operator Application Certification:
I hereby certify that the information submitted with this application is true, accurate and complete to the best of my knowledge and belief.
Name (Print): Title:
Signature: Date:
e-mail address: Telephone:
OCD Approval: Permit Application (including closure plan) Closure Plan (only) OCD Conditions (see attachment) OCD Representative Signature: Approval Date: 2/15/11 Title: OCD Permit Number:
Closure Report (required within 60 days of closure completion): Subsection K of 19.15.17.13 NMAC Instructions: Operators are required to obtain an approved closure plan prior to implementing any closure activities and submitting the closure report. The closure report is required to be submitted to the division within 60 days of the completion of the closure activities. Please do not complete this section of the form until an approved closure plan has been obtained and the closure activities have been completed. X Closure Completion Date: June 23, 2010
22 Closure Method: Waste Excavation and Removal X On-site Closure Method Alternative Closure Method Waste Removal (Closed-loop systems only) If different from approved plan, please explain.
Closure Report Regarding Waste Removal Closure For Closed-loop Systems That Utilize Above Ground Steel Tanks or Haul-off Bins Only: Instructions: Please identify the facility or facilities for where the liquids, drilling fluids and drill cuttings were disposed. Use attachment if more than two facilities were utilized. Disposal Facility Name: Disposal Facility Permit Number: Were the closed-loop system operations and associated activities performed on or in areas that will not be used for future service and operations? Yes (If yes, please demonstrate complilane to the items below) Required for impacted areas which will not be used for future service and operations: Site Reclamation (Photo Documentation) Soil Backfilling and Cover Installation Re-vegetation Application Rates and Seeding Technique
Closure Report Attachment Checklist: Instructions: Each of the following items must be attached to the closure report. Please indicate, by a check mark in the box, that the documents are attached. X Proof of Closure Notice (surface owner and division) X Proof of Deed Notice (required for on-site closure) X Plot Plan (for on-site closures and temporary pits) X Confirmation Sampling Analytical Results (if applicable) Waste Material Sampling Analytical Results (if applicable) X Disposal Facility Name and Permit Number X Soil Backfilling and Cover Installation X Re-vegetation Application Rates and Seeding Technique X Site Reclamation (Photo Documentation) On-site Closure Location: Latitude: 36.787032 °N Longitude: 107.348592 °W NAD 1927 X 1983
25
Operator Closure Certification: I hereby certify that the information and attachments submitted with this closure report is ture, accurate and complete to the best of my knowledge and belief. I also certify that the closure complies with all applicable closure requirements and conditions specified in the approved closure plan. Name (Print): Signature: Date: e-mail address: mante.e.jaramillo@corocophillos.com Telephone: 505-326-9865

ConocoPhillips Company San Juan Basin Closure Report

Lease Name: SAN JUAN 30-5 UNIT 81N

API No.: 30-039-30765

In accordance with Rule 19.15.17.13 NMAC the following information describes the closure of the temporary pit referenced above. All proper documentation regarding closure activities is being included with the C-144. The temporary pit for this location was constructed and location drilled before June 16, 2008 (effective date for Rule 19.15.17). While closure of the temporary pit did fall within the rule some dates for submittals are after the rig release date.

- Details on Capping and Covering, where applicable. (See report)
- Plot Plan (Pit Diagram) (Included as an attachment)
- Inspection Reports (Included as an attachment)
- Sampling Results (Included as an attachment)
- C-105 (Included as an attachment)
- Copy of Deed Notice will be filed with County Clerk (Not required on Federal, State, or Tribal land as stated by FAQ dated October 30, 2008)

General Plan:

1. All free standing liquids will be removed at the start of the pit closure process from the pit and disposed of in a division—approved facility or recycle, reuse or reclaim the liquids in a manner that the appropriate division district office approves.

All recovered liquids were disposed of at Basin Disposal (Permit #NM-01-005) and any sludge or soil required to be removed to facilitate closure was hauled to Envirotech Land Farm (Permit #NM-01-011) and JFJ Landfarm % IEI (Permit #NM-01-0010B).

2. The preferred method of closure for all temporary pits will be on-site burial, assuming that all the criteria listed in sub-section (B) of 19.15.17.13 are met.

The pit was closed using onsite burial.

3. The surface owner shall be notified of COPC's closing of the temporary pit as per the approved closure plan using certified mail, return receipt requested.

The closure process notification to the landowner was sent via certified mail. (See Attached)(Well located on Private Land, certified mail is not required for Federal Land per BLM/OCD MOU.)

4. Within 6 months of the Rig Off status occurring COPC will ensure that temporary pits are closed, re-contoured, and reseeded.

Provision 4 of the closure plan requirements were not met due to rig move off date as noted on C-105 which was prior to pit rule change. ConocoPhillips will ensure compliance with this rule in the future.

- 5. Notice of Closure will be given to the Aztec Division office between 72 hours and one week of closure via email, or verbally. The notification of closure will include the following:
 - i. Operator's name
 - ii. Location by Unit Letter, Section, Township, and Range. Well name and API number.

Notification is attached.

6. Liner of temporary pit shall be removed above "mud level" after stabilization. Removal of liner will consist of manually or mechanically cutting liner at mud level and removing all remaining liner. Care will be taken to remove "All" of the liner i.e., edges of liner entrenched or buried. All excessive liner will be disposed of at a licensed disposal facility.

Liner of temporary pit was removed above "mud level" after stabilization. Removal of the liner consisted of manually cutting liner at mud level and removing all remaining liner. Care was taken to remove "ALL" of the liner i.e., edges of liner entrenched or buried. All excessive liner was disposed of at a licensed disposal facility, (San Juan County Landfill).

7. Pit contents shall be mixed with non-waste containing, earthen material in order to achieve the solidification process. The solidification process will be accomplished using a combination of natural drying and mechanically mixing. Pit contents will be mixed with non-waste, earthen material to a consistency that is deemed a safe and stable. The mixing ratio shall not exceed 3 parts clean soil to 1 part pit contents.

ConocoPhillips mixed the Pit contents with non-waste containing, earthen material in order to achieve the solidification process. The solidification process was accomplished by using a combination of natural drying and mechanically mixing. Pit contents were mixed with non-waste, earthen material to a consistency that is deemed as safe and stable. The mixing ratio consisted of approximately 3 parts clean soil to 1 part pit contents.

8. A five point composite sample will be taken of the pit using sampling tools and all samples tested per Subsection B of 19.15.17.13(B)(1)(b). In the event that the criteria are not met, all contents will be handled per Subparagraph (a) of Paragraph (1) of Subsection B of 19.15.17.13 i.e., Dig and haul.

A five point composite sample was taken of the pit using sampling tools and all samples tested per Subsection B of 19.15.17.1 3(B)(1)(b). (Sample results attached).

Components	Tests Method	Limit (mg/Kg)	Results
Benzene	EPA SW-846 8021B or 8260B	0.2	2.8 ND ug/kg
BTEX	EPA SW-846 8021B or 8260B	50	/4/ N/O ug/kG
TPH	EPA SW-846 418.1	2500	321 24:3mg/kg
GRO/DRO	EPA SW-846 8015M	580	109 6.0 mg/Kg
Chlorides	EPA 300.1	(1000/\$00	/90 56 mg/L

9. Upon completion of solidification and testing standards being passed, the pit area will be backfilled with compacted, non-waste containing, earthen material. A minimum of four feet of cover shall be achieved and the cover shall include one foot of suitable material to establish vegetation at the site, or the background thickness of topsoil, whichever is greater. If standard testing fails BR will dig and haul all contents pursuant to 19.15.17.13.i.a. After doing such, confirmation sampling will be conducted to ensure a release has not occurred.

The pit material passed solidification and testing standards. The pit area was then backfilled with compacted, non-waste containing, earthen material. More than four feet of cover was achieved and the cover included one foot of suitable material to establish vegetation at the site.

10. During the stabilization process if the liner is ripped by equipment the Aztec OCD office will be notified within 48 hours and the liner will be repaired if possible. If the liner can not be repaired then all contents will be excavated and removed.

The integrity of the liner was not damaged in the pit closure process.

11. Dig and Haul Material will be transported to the Envirotech Land Farm located 16 miles south of Bloomfield on Angel Peak Road, CR 7175. Permit # NM010011

Dig and Haul was not required.

12. Re-contouring of location will match fit, shape, line, form and texture of the surrounding. Re-shaping will include drainage control, prevent ponding, and prevent erosion. Natural drainages will be unimpeded and water bars and/or silt traps will be place in areas where needed to prevent erosion on a large scale. Final recontour shall have a uniform appearance with smooth surface, fitting the natural landscape.

The pit area was re-contoured to match fit, shape, line, form and texture of the surrounding area. Re-shaping included drainage control, to prevent ponding and erosion. Natural drainages were unimpeded and water bars and/or silt traps were placed in areas where needed to prevent erosion on a large scale. Final recontour has a uniform appearance with smooth surface, fitting the natural landscape.

13. Notification will be sent to OCD when the reclaimed area is seeded.

Provision 13 was accomplished on 07/07/10 with the following seeding regiment:

Туре	Variety or Cultivator	PLS/A
Western wheatgrass	Arriba	3.0
Indian ricegrass	Paloma or Rimrock	3.0
Slender wheatgrass	San Luis	2.0
Crested wheatgrass	Hy-crest	3.0
Bottlebrush Squirreltail	Unknown	2.0
Four-wing Saltbrush	Delar	.25

14. COPC shall seed the disturbed areas the first growing season after the operator closes the pit. Seeding will be accomplished via drilling on the contour whenever practical or by other division-approved methods. BLM or Forest Service stipulated seed mixes will used on federal lands. Vegetative cover will equal 70% of the native perennial vegetative cover (un-impacted) consisting of at least three native plant species, including at least one grass, but not including noxious weeds, and maintain that cover through two successive growing seasons. Repeat seeding or planting will be continued until successful vegetative growth occurs.

Provision 14 was accomplished on 07/07/10 with the above seeding regiment. Seeing was accomplished via drilling on the contour whenever practical or by other division-approved methods. The OCD will be notified once two successive growing seasons have been accomplished by submitting a C-103.

15. The temporary pit will be located with a steel marker, no less than four inches in diameter, cemented in a hole three feet deep in the center of the onsite burial upon the abandonment of all the wells on the pad. The marker will be flush with the ground to allow access of the active well pad and for safety concerns. The marker will include a threaded collar to be used for future abandonment. The top of the marker will contain a welded steel 12" square plate that indicates the onsite burial of the temporary pit. The plate will be easily removable and a four foot tall riser will be threaded into the top of the collar marker and welded around the base with the operator's information at the time of all wells on the pad are abandoned. The operator's information will include the following: Operator Name, Lease Name, Well Name and number, Unit Number, Section, Township, Range and an indicator that the marker is an onsite burial location.

Provision 15 was accomplished by installing a steel marker in the temporary pit, no less than four inches in diameter, cemented in a hole three feet deep in the center of the onsite burial. The marker is flush with the ground to allow access of the active well pad and for safety concerns. The top of the marker contains a welded steel 12" square plate that indicates the onsite burial of the temporary pit. The plate contains the following: Operator Name, Lease Name, Well Name and number, Unit Number, Section, Township, Range and an indicator that the marker is an onsite burial location.

The plate will be easily removable and a four foot tall riser will be threaded into the top of the collar marker and welded around the base with the following operator's information at the time of all wells on the pad are abandoned. The riser will be labeled: COP, Fee, SAN JUAN 30-5 UNIT 81N, UL-F, Sec. 27, T 30N, R 5W, API # 30-039-30765



ConocoPhillips Company CRE/PTRRC – San Juan Business Unit Juanita Farrell 3401 East 30th Street Farmington, NM 87402 Telephone: (505) 326-9597 Facsimile: (505) 324-6136

May 15, 2009

VIA CERTIFIED MAIL – RETURN RECEIPT REQUESTED 7179-1000-1641-0022-4386

Amy Yvette Moreno 6 CR 5778 Farmington, NM 87499

Re:

San Juan 30-5 Unit 81N NW Section 27, T30N, R5W Rio Arriba County, New Mexico

Dear Ms. Moreno:

Pursuant to Paragraph 1 (b) of Subsection F of 19.15.17.13 NMAC, an operator shall provide the surface owner notification of the operator's proposal to close a temporary pit on-site in compliance with the on-site closure methods specified in the same Subsection of the NMAC. In compliance of this requirement, please consider this notification of ConocoPhillips' intent to close the temporary pit on the above referenced location.

If you have any questions, please contact Elmo Seabolt at (505) 326-9554. Sincerely,

Juanita Farrell

Juanita Farrell Staff Associate, PTRRC STATE OF NEW MEXICO COUNTY OF RIO ARRIBA

RECORDATION NOTICE OF PIT BURIAL

In accordance with Section 19.15.17.13.F.1.f of the NMAC, operator hereby provides notice in the public record of an on-site burial of a temporary pit at the following location:

> Well Name: San Juan 30-5 Unit 81N Latitude: 36.786963 N Longitude: 107.348285W Unit Letter(1/4, 1/4): F Section: 27 Township: 30N Range: 5W County: Rio Arriba State: NM

IN WITNESS WHEREOF, this Recordation Notice of Pit Burial has been executed on the date indicated below by the undersigned.

CONOCOPHILLIPS COMPANY

Mike L. Mankin. Supervisor, PTRRC

STATE OF NEW MEXICO

COUNTY OF SAN JUAN

This instrument was acknowledged before me this 2nd day of August, 2010, by Mike ConocoPhillips Company, on behalf of said corporation.

My Commission Expires: /0 JAN 2.0/9

Notary Public

RIO ARRIBA COUNTY CLERK MOISES A MORALES JR

KASALAZAR



District I
1625 N. French Dr., Hobbs, NM 88240
District II

1301 W. Grand Avenue, Artesia, NM 88210 District III

1000 Rio Brazos Rd., Aztec, NM 87410 District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Mincrals & Natural Resources Department
OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505


Form C-102 Revised October 12, 2005 Submit to Appropriate District Office State Lease - 7 Copies Fee Lease - 3 Copies

☐ AMENDED REPORT

WELL LOCATION AND ACREAGE DEDICATION PLAT

¹ A	PI Number		2	Pool Code	BASIN DAKOTA / BLANCO MESAVERDE				RDE
⁴ Property Cod	le	5 Property Name SAN JUAN 30-5 UNIT					⁶ Well Number 81N		
7 OGRID No	o.	8 Operator Name CONOCOPHILLIPS COMPANY						⁹ Elevation 6576	
					¹⁰ SURFACE	LOCATION			
UL or lot no. F	Section 27	Township 30-N	Range 5-W	Lot Idn	Feet from the 1525	North/South line NORTH	Feet from the 1620	East/West line WEST	County RIO ARRIBA
			11 E	ottom H	ole Location	If Different Fro	m Surface		
UL or lot no.	Section	Township	Range	Lot Idn	Feet from the	North/South line	Feet from the	East/West line	County
Dedicated Acres 320.00	13 Joint o	or Infill 14	Consolidation	Code 15	Order No.				

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION




S. C.C.I. SURVEYS IS NOT LIABLE FOR UNDERGROUND UTILITIES OR PIPELINES.

CONTRACTOR SHOULD CALL ONE—CALL FOR LOCATION OF ANY MARKED OR UNMARKED BURIED

PIPELINES OR CABLES ON WELL PAD AND OR ACCESS ROAD AT LEAST TWO (2) WORKING DAYS PRIOR TO CONSTRUCTION.

1 BESEBAE BIT DIKE: TO BE 8' ABOVE DEEP SIDE (OVERFLOW-3' WIDE AND 1' ABOVE SHALLOW SIDE).





EPA METHOD 8015 Modified Nonhalogenated Volatile Organics Total Petroleum Hydrocarbons

Client:	ConocoPhillips	Project #:	96052-1706
Sample ID:	Background	Date Reported:	05-10-10
Laboratory Number:	54038	Date Sampled:	05-05-10
Chain of Custody No:	8994	Date Received:	05-05-10
Sample Matrix:	Soil	Date Extracted:	05-07-10
Preservative:	Cool	Date Analyzed:	05-07-10
Condition:	Intact	Analysis Requested:	8015 TPH

Parameter Gasoline Range (C5 - C10) Diesel Range (C10 - C28)	Concentration (mg/Kg)	Det. Limit (mg/Kg)
Gasoline Range (C5 - C10)	ND	0.2
Diesel Range (C10 - C28)	6.0	0.1
Total Petroleum Hydrocarbons	6.0	0.2

ND - Parameter not detected at the stated detection limit.

References:

Method 8015B, Nonhalogenated Volatile Organics, Test Methods for Evaluating Solid Waste,

SW-846, USEPA, December 1996.

Comments:

S.J. 30-5 Unit #81N



EPA METHOD 8015 Modified Nonhalogenated Volatile Organics **Total Petroleum Hydrocarbons**

Client:	ConocoPhillips	Project #:	96052-1706
Sample ID:	Reserve Pit	Date Reported:	05-10-10
Laboratory Number:	54039	Date Sampled:	05-05-10
Chain of Custody No:	8994	Date Received:	05-05-10
Sample Matrix:	Soil	Date Extracted:	05-07-10
Preservative:	Cool	Date Analyzed:	05-07-10
Condition:	Intact	Analysis Requested:	8015 TPH

Parameter	Concentration (mg/Kg)	Det. Limit (mg/Kg)
Gasoline Range (C5 - C10)	23.0	0.2
Diesel Range (C10 - C28)	86.0	0.1
Total Petroleum Hydrocarbons	109	0.2

ND - Parameter not detected at the stated detection limit.

References:

Method 8015B, Nonhalogenated Volatile Organics, Test Methods for Evaluating Solid Waste,

SW-846, USEPA, December 1996.

Comments:

S.J. 30-5 Unit #81N



EPA Method 8015 Modified Nonhalogenated Volatile Organics Total Petroleum Hydrocarbons

Quality Assurance Report

Client:	QA/QC		Project #:		N/A
Sample ID:	05-07-10 QA/0	nc.	Date Reported:		05-10-10
Laboratory Number:	54015	, C	Date Sampled:		N/A
Sample Matrix:	Methylene Chlor	ida	Date Received:		N/A
Preservative:	N/A	100	Date Analyzed:		05-07-10
Condition:	N/A		Analysis Reques	tod:	TPH
Condition.	IN/A		Allalysis Reques	ilea.	i F TI
	l-©al(Date	i-Cal RF:	C-Cal RF	% Difference	Accept Range
Constitute Parama CF C40	and the second s	1.0645E+003	1.0649E+003	0.04%	0 - 15%
Gasoline Range C5 - C10	05-07-07				
Diesel Range C10 - C28	05-07-07	1.0278E+003	1.0282E+003	0.04%	0 - 15%
Disal Good (mail mail of				Detection Limi	3
Blank Conc. (mg/L - mg/Kg)		-Concentration			
Gasoline Range C5 - C10		ND		0.2	
Diesel Range C10 - C28		ND		0.1	
Total Petroleum Hydrocarbons		ND		0.2	
					2 1
Duplicate Conc. (mg/Kg)	Sample	Duplicate	% Difference	Accept Range	
Gasoline Range C5 - C10	ND	ND	0.0%	0 - 30%	
Diesel Range C10 - C28	ND	ND	0.0%	0 - 30%	
Spike Conc. (mg/Kg)	Sample	Spike Added	Spike Result	% Recovery	-Accept Range
Gasoline Range C5 - C10	ND	250	253	101%	75 - 125%
Diesel Range C10 - C28	ND	250	256	102%	75 - 125%
Gasoline Range C5 - C10	ND	250	253	101%	75 - 125

ND - Parameter not detected at the stated detection limit.

References:

Method 8015B, Nonhalogenated Volatile Organics, Test Methods for Evaluating Solid Waste,

SW-846, USEPA, December 1996.

Comments:

QA/QC for Samples 54015 - 54016 and 54038 - 54045.

Apalyst

Review



EPA METHOD 8021 AROMATIC VOLATILE ORGANICS

Client:	ConocoPhillips	Project #:	96052-1706
Sample ID:	Background	Date Reported:	05-10-10
Laboratory Number:	54038	Date Sampled:	05-05-10
Chain of Custody:	8994	Date Received:	05-05-10
Sample Matrix:	Soil	Date Analyzed:	05-07-10
Preservative:	Coal	Date Extracted:	05-07-10
Condition:	Intact	Analysis Requested:	BTEX

Parameter	Concentration (ug/Kg)	Det. Limit (ug/Kg)	
Benzene	ND	0.9	
Toluene	ND	1.0	
Ethylbenzene	ND	1.0	
p,m-Xylene	ND	1.2	
o-Xylene	ND	0.9	
Total BTEX	NĐ		

ND - Parameter not detected at the stated detection limit.

Surrogate Recoveries:	Parameter	Percent Recovery	
	Fluorobenzene	94.4 %	
	1,4-difluorobenzene	95.7 %	
	Bromochlorobenzene	106 %	

References:

Method 5030B, Purge-and-Trap, Test Methods for Evaluating Solid Waste, SW-846, USEPA,

December 1996.

Method 8021B, Aromatic Volatile Organics, Test Methods for Evaluating Solid Waste, SW-846,

USEPA, December 1996.

Comments:

S.J. 30-5 Unit #81N

Danda Juli

Mustur Mulaeten



EPA METHOD 8021 AROMATIC VOLATILE ORGANICS

Client:	ConocoPhillips	Project #:	96052-1706
Sample ID:	Reserve Pit	Date Reported:	05-10-10
Laboratory Number:	54039	Date Sampled:	05-05-10
Chain of Custody:	8994	Date Received:	05-05-10
Sample Matrix:	Soil	Date Analyzed:	05-07-10
Preservative:	Cool	Date Extracted:	05-07-10
Condition:	Intact	Analysis Requested:	BTEX

Parameter	Concentration (ug/Kg)	Det. Limit (ug/Kg)	
Benzene	2.8	0.9	
Toluene	15.0	1.0	
Ethylbenzene	9.0	1.0	
p,m-Xylene	80.5	1.2	
o-Xylene	33.4	0.9	
Total RTFY	141		

ND - Parameter not detected at the stated detection limit.

Surrogate Recoveries:	Parameter	Percent Recovery
	Fluorobenzene	92.9 %
	1,4-difluorobenzene	92.7 %
	Bromochlorobenzene	100 %

References:

Method 5030B, Purge-and-Trap, Test Methods for Evaluating Solid Waste, SW-846, USEPA,

December 1996.

Method 8021B, Aromatic Volatile Organics, Test Methods for Evaluating Solid Waste, SW-846,

USEPA, December 1996.

Comments:

S.J. 30-5 Unit #81N

Dender July



EPA METHOD 8021 AROMATIC VOLATILE ORGANICS

Client:	N/A	Project #:	N/A
Sample ID:	05-07-BTX QA/QC	Date Reported:	05-10-10
Laboratory Number:	54015	Date Sampled:	N/A
Sample Matrix:	Soil '	Date Received:	N/A
Preservative:	N/A	Date Analyzed:	05-07-10
Condition:	N/A	Analysis:	BTEX

Calibration and Detection Limits (ug/L)		C-Cal RF: Accept. Rand	%Diff. je:0 - 15%	Blank Conc	Detect Limit
Benzene	1.2972E+006	1,2998E+006	0.2%	ND	0.1
Toluene	1.2007E+006	1.2031E+006	0.2%	ND	0.1
Ethylbenzene	1.0727E+006	1,0749E+006	0.2%	ND	0.1
p,m-Xylene	2.6560E+006	2.6613E+006	0.2%	ND	0.1
o-Xylene	1.0175E+006	1.0196E+006	0.2%	ND	0.1

Duplicate Conc. (ug/Kg)	Sample Du	olicate	%Diff.	Accept Range	Detect Limit
Benzene	ND	ND	0.0%	0 - 30%	0.9
Toluene	ND	ND	0.0%	0 - 30%	1.0
Ethylbenzene	ND	ND	0.0%	0 - 30%	1.0
p,m-Xylene	ND	ND	0.0%	0 - 30%	1.2
o-Xylene	ND	ND	0.0%	0 - 30%	0.9

Spike Conc. (ug/Kg)	Sample Amo	unt Spiked Spik	ed Sample	% Recovery	-Accept Range
Benzene	ND	50.0	48.1	96.2%	39 - 150
Toluene	ND	50.0	48.3	96.6%	46 - 148
Ethylbenzene	ND	50.0	47.5	95.0%	32 - 160
p,m-Xylene	ND	100	95.4	95.4%	46 - 148
o-Xylene	ND	50.0	47.7	95.4%	46 - 148

ND - Parameter not detected at the stated detection limit.

References:

Method 5030B, Purge-and-Trap, Test Methods for Evaluating Solid Waste, SW-846, USEPA,

Method 8021B, Aromatic and Halogenated Volatiles by Gas Chromatography Using Photoionization and/or Electrolytic Conductivity Detectors, SW-846, USEPA December 1996.

Comments:

QA/QC for Samples 54015 - 54016 and 54038 - 54045.



EPA METHOD 418.1 TOTAL PETROLEUM HYDROCARBONS

Client:	ConocoPhillips	Project #:	96052-1706
Sample ID:	Background	Date Reported:	05-10-10
Laboratory Number:	54038	Date Sampled:	05-05-10
Chain of Custody No:	8994	Date Received:	05-05-10
Sample Matrix:	Soil	Date Extracted:	05-07-10
Preservative:	Cool	Date Analyzed:	05-07-10
Condition:	Intact	Analysis Needed:	TPH-418.1

		Det.
	Concentration	Limit
Parameter	(mg/kg)	(mg/kg)

Total Petroleum Hydrocarbons

24.3

21.6

ND = Parameter not detected at the stated detection limit.

References:

Method 418.1, Petroleum Hydrocarbons, Total Recoverable, Chemical Analysis of Water

and Waste, USEPA Storet No. 4551, 1978.

Comments:

S.J. 30-5 Unit #81N



EPA METHOD 418.1 TOTAL PETROLEUM HYDROCARBONS

Client:	ConocoPhillips	Project #:	96052-1706
Sample ID:	Reserve Pit '	Date Reported:	05-10-10
Laboratory Number:	54039	Date Sampled:	05-05-10
Chain of Custody No:	8994	Date Received:	05-05-10
Sample Matrix:	Soil	Date Extracted:	05-07-10
Preservative:	Cool	Date Analyzed:	05-07-10
Condition:	Intact	Analysis Needed:	TPH-418.1

		Det.
	Concentration	Limit
Parameter	(mg/kg)	(mg/kg)

Total Petroleum Hydrocarbons

321

21.6

ND = Parameter not detected at the stated detection limit.

References:

Method 418.1, Petroleum Hydrocarbons, Total Recoverable, Chemical Analysis of Water

and Waste, USEPA Storet No. 4551, 1978.

Comments:

S.J. 30-5 Unit #81N



EPA METHOD 418.1 TOTAL PETROLEUM HYROCARBONS QUALITY ASSURANCE REPORT

Client: QA/QC Project #: N/A Sample ID: QA/QC 05-07-10 Date Reported: Laboratory Number: 05-07-TPH.QA/QC 54038 Date Sampled: N/A Sample Matrix: Freon-113 Date Analyzed: 05-07-10 Preservative: N/A 05-07-10 Date Extracted: Condition: N/A Analysis Needed: **TPH**

Blank Conc. (mg/Kg) Concentration Detection Limit **TPH** ND 21.6 Duplicate Conc. (mg/Kg) Sample Duplicate % Difference Accept. Range **TPH** 24.3 25.7 5.8% +/- 30% Spike Conc. (mg/Kg) Spike Added Spike Result % Recovery Accept Range Sample **TPH** 24.3 2,000 1,790 88.4% 80 - 120%

ND = Parameter not detected at the stated detection limit.

References:

Method 418.1, Petroleum Hydrocarbons, Total Recoverable, Chemical Analysis of Water

and Waste, USEPA Storet No. 4551, 1978.

Comments:

QA/QC for Samples 54037 - 54043, 54049, 54050 and 54073.

Analyst

Mustle Mullers Review



Chloride

Client:	ConocoPhillips	Project #:	96052-1706
Sample ID:	Background	Date Reported:	05-10-10
Lab ID#:	54038	Date Sampled:	05-05-10
Sample Matrix:	Soil '	Date Received:	05-05-10
Preservative:	Cool	Date Analyzed:	05-07-10
Condition:	Intact	Chain of Custody:	8994

Parameter Concentration (mg/Kg)

Total Chloride

50

Reference:

U.S.E.P.A., 4500B, "Methods for Chemical Analysis of Water and Wastes", 1983. Standard Methods For The Examination of Water And Waste Water", 18th ed., 1992.

Comments:

S.J. 30-5 Unit #81N

Analyst

Review



Chloride

96052-1706 Client: ConocoPhillips Project #: Reserve Pit Date Reported: 05-10-10 Sample ID: Lab ID#: 54039 Date Sampled: 05-05-10 Sample Matrix: Soil Date Received: 05-05-10 05-07-10 Preservative: Date Analyzed: Cool Condition: Intact Chain of Custody: 8994

Parameter |

Concentration (mg/Kg)

Total Chloride

190

Reference:

U.S.E.P.A., 4500B, "Methods for Chemical Analysis of Water and Wastes", 1983.

Standard Methods For The Examination of Water And Waste Water", 18th ed., 1992.

Comments:

S.J. 30-5 Unit #81N

Analyst

Review

Submit To Appropr Two Copies	iate Distric	t Office		,		State of Ne											rm C-105
District I 1625 N. French Dr.	. Hobbs, N	M 88240		Ene	ergy, l	Minerals and	i Na	tural	Re	sources	-	1. WELL A	NDI N	NO.		<u>J</u>	uly 17, 2008
District II 1301 W. Grand Ave			10		0''	1.0		ъ.				30-039-307		NO.			
District III						l Conservat					t	2. Type of Le	ase				
1000 Rio Brazos Ro District IV						20 South St				r.	-	3. State Oil &		FEE		ED/INDI	AN
1220 S. St. Francis	Dr., Santa	Fe, NM 875	05			Santa Fe, N	NIVI	8/3(JS			SF-078738	Gas	Lease No	' .		
WELL	COMP	LETIO	V OR F	RECO	MPL	ETION REI	POF	RT A	NE	LOG		de la lita					
4. Reason for fili	ng:											5. Lease Name			ement Na	me	
☐ COMPLETI	ON REP	ORT (Fil	in boxes	#1 throu	gh #31	for State and Fee	well	s only))		ŀ	6. Well Numb		5 UNII			
C-144 CLOS #33; attach this ar	nd the pla										r	81N					
7. Type of Comp ✓ NEW V] WORK	OVER [DEEPE	ENING	□PLUGBACE		DIFFE	ERE	NT RESERVO	OIR	OTHER					
8. Name of Opera	itor	-										9. OGRID					
ConocoPhilli 10. Address of Or		pany									\dashv	217817	or W	ildeat			
PO Box 4298, Fa	rmington		9										01 111				
12.Location	Unit Ltr	Sect	on	Towns	hip	Range	Lot			Feet from th	e	N/S Line	Feet	from the	E/W L	ine	County
Surface:											_						
BH:	114.5	T.D. D	1 1	15.5	Note: Dis	D-1			1.0	D. C. I	إ	(D. 1 . D. 1			7.51	(Dr	LDVD
13. Date Spudded	l	ate T.D. R	eached	09/2	1/09	Released	+la			<u> </u>		(Ready to Prod	· · ·	R	T, GR, et	c.)	and RKB,
18. Total Measure	ea Deptn	or well		19. F	ing Bac	ck Measured Dep	otn		20.	was Direction	ona	l Survey Made?		21. tyj	pe Electri	c and Ot	her Logs Run
22. Producing Int	erval(s),	of this con	pletion - '	Γop, Bot	tom, Na	ame											
23.					CAS	ING REC	OR	D (R	lep	ort all stri	ng	gs set in we	ell)				
CASING SIZ	ZE	WEIG	GHT LB./I			DEPTH SET				LE SIZE		CEMENTIN		CORD	AM	IOUNT	PULLED
SIZE	TOP		ROT	том	LIN	ER RECORD SACKS CEM	ENT	SCR	PEEN		25. SIZ			NG REC		PACKE	DCET
SIZE	101		100	TOM		SACKS CEM	CITI	John	CLLI	<u>`</u>	J12		10,	JI III JE		TACK	EK SE1
26. Perforation	record (ii	nterval, siz	e, and nui	nber)							R/	ACTURE, CE					
								DEF	111	INTERVAL		AMOUNT A	NUN	IND MA	TERIAL	Uacu	
						•											
												<u> </u>					····
28.	41		D., 1	' M-4	- 1 (FI					FION		W H Co. a	<u>(D</u>				
Date First Produc	uon		Product	ion ivieu	10a (<i>F1</i> 6	owing, gas lift, pt	итріп					Well Status	(Prot	i. or Shui	(-in)		
Date of Test	Hours	Tested	Cho	ke Size		Prod'n For Test Period		Oil -	- Bbl		Gas	- MCF	W:	ater - Bbl		Gas - C	il Ratio
Flow Tubing	Casin	g Pressure	Cal	culated 2	24-	Oil - Bbl.		<u></u>	Gas	- MCF	_	Water - Bbl.		Oil Gr	avity - AF	I - (Cor	r.)
Press.				ır Rate				1			1				•		<i>_</i>
29. Disposition of	Gas (So	ld, used fo	fuel, veni	ted, etc.)		l						<u> </u>	30. 1	est Witn	essed By		
31. List Attachme	ents																
32. If a temporary	pit was	used at the	well, atta	ch a plat	with th	e location of the	temp	orary p	oit.								
33. If an on-site b	urial was		1	4 4						7.000 F7.00							
I hereby certif	Sy that to	Latit he inforr	ude 36.78	17 07/2/ /N holwin c	Loi an hoth	ngitude 107.348 h sides of this	592°\ forn	W NA n is tr	ND [te	to the hest o	f mv	knowle	dge and	l heliet	
Signature	Mar	WW/	ma		' Prir					-		_	-		e: 7/30/2	-	:
E-mail Addre	ss mari	e.e.jaran	fillo@co	onocon	hillips	s.com											į
			1	r		·		-									
		\sim															

ConocoPhillips

Pit Closure Form:	
Date: <u>6/23/2010</u>	
Well Name: <u>SJ 30</u>	-5 8IN \$ 81P
Footages:	Unit Letter:
	RW, County: R.A. State: WM
Contractor Closing Pit:	R:Her
Construction Inspector:	Norman tava Date: 20/23/10
Inspector Signature:	Norman For

Revised 4/30/10

Jaramillo, Marie E

From:

Payne, Wendy F

Sent:

Wednesday, May 26, 2010 11:38 AM

To:

(Brandon.Powell@state.nm.us); 'brook@crossfire-llc.com'; GRP:SJBU Regulatory; 'Isaiah Lee'; 'tevans48@msn.com'; Blair, Maxwell O; Blakley, Mac; Clark, Joni E; Farrell, Juanita R; Gillette, Steven L (Gray Surface Specialties and Consulting, Ltd.); Greer, David A; Hines, Derek J (Finney Land Co.); Maxwell, Mary Alice; McWilliams, Peggy L; Seabolt, Elmo F; Stallsmith, Mark R; (bko@digii.net); Mark Kelly; Robert Switzer; Sherrie Landon; Bassing, Kendal R.; Chavez, Virgil E; Elmer Perry; Faver Norman; Fred Martinez; Jared Chavez; Lowe, Terry; Payne, Wendy F; Silverman, Jason M; Spearman, Bobby E; 'Steve McGlasson'; Tally, Ethel; Becker, Joey W; Bowker, Terry D; Gordon Chenault; GRP:SJBU Production Leads; Hockett, Christy R; Johnson, Kirk L; Bassing, Kendal R.; Kennedy, Jim R; Lopez, Richard A; O'Nan, Mike J.; Peace, James T; Pierce, Richard M; Poulson, Mark E; Smith, Randall O;

Spearman, Bobby E; Stamets, Steve A; Thacker, LARRY; Work, Jim A

Cc:

'jdritt@aol.com'

Subject:

Reclamation Notice: San Juan 30-5 Unit 81N & San Juan 30-5 Unit 81P

Importance:

High

Attachments:

San Juan 30-5 Unit 81N & 81P.pdf

JD Ritter will move a tractor to the **San Juan 30-5 Unit 81N & San Juan 30-5 Unit 81P** (same location) to start the reclamation process on Tuesday, June 1st, 2010. Please contact Norm Faver (320-0670) if you have questions or need further assistance. Driving directions are attached. **Please insure that all work is split between the two network numbers listed below. Thank you.**



San Juan 30-5 Unit 81N & 81P.p...

ConocoPhillips Well- Network #: 10244539 - Activity Code D250 (reclamation) & D260 (pit closure)

Rio Arriba County, NM

SAN JUAN 30-5 UNIT 81N - FEE surface / BLM minerals

Twin: San Juan 30-5 Unit 81P

1525' FNL, 1620' FWL

SEC. 27, T30N, R05W

Unit Letter 'F'

Lease #: NM SF-078738

Latitude: 36° 47 min 12.27120 sec N (NAD 83)

Longitude: 107° 20 min 53.63160 sec W (NAD83)

Total Acres Disturbed: 3.347 acres

Access Road: 1971.5'

API #: 30-039-30765

ConocoPhillips Well- Network #: 10261989 - Activity code D250 (reclamation) & D260 (pit closure)

Construction Inspector: Stan Mobley (330-3425)

FLINT will build the following location in Rio Arriba County, NM

SAN JUAN 30-5 UNIT 81P - FEE surface / FEE minerals

Twin: San Juan 30-5 Unit 81N

1505' FNL, 1550' FWL

SEC. 27, T30N, R05W

Unit Letter 'F'

Lease #: FEE

Latitude: 36° 47 min 12.43680 sec N (NAD 83)

Longitude: 107° 20 min 54.48840 sec W (NAD83)

Total Acres Disturbed: 3.347 acres

Access Road: 1971.5'


Wendy Payne
ConocoPhillips-SJBU
505-326-9533
Wendy.F.Payne@conocophillips.com

ConocoPhillips

Reclamation Form:
Date: 7/13/10
Well Name: SJ 30-5 81N -81P
Footages: Unit Letter:
Section:, T- <u>30</u> -N, R- <u>5</u> -W, County: <u>k.A.</u> State: <u>NM</u>
Reclamation Contractor:
Reclamation Date: 7/5/10
Road Completion Date: 7/5/10
Seeding Date: 7/7/10
**PIT MARKER STATUS (When Required):
MARKER PLACED: 7/14 (DATE)
LATATUDE:
LONGITUDE:
Construction Inspector: Norman Faver Date: 7/13/10
Inspector Signature:









WELL PAD SAFETY AND ENVIRONMENTAL CHECK LIST

WELL NAME: SAN JUAN 30-5 UNIT 81N

API#: 30-039-30765

COMMENTS	RIG ON LOCATION	RIG ON LOCATION	FENCE & LINER IN GOOD CONDITION; RIG JUST OFF, APRON NOT CUT BACK YET	FENCE CUT & NOT REPAIRED PROPERLY; BARBED-WIRE CUT; P SMALL HOLES IN LINER	LINER IN GOOD CONDITION; GAP UNDERNEATH FENCE ON R SIDE OF PIT T- POST LOOSE ON E SIDE ON PIT	LINER IN GOOD CONDITION; GAP UNDERNEATH FENCE ON R SIDE OF PIT; TPOSTS LOOSE ON E SIDE OF PIT	FENCE & LINER IN GOOD CONDITION	RIG ON LOCATION	RIG ON LOCATION	FENCE & LINER IN GOOD CONDITION	FRAC CREW ON LOCATION
PICTURES TAKEN	×	×	×	×	×	×		×	×	×	×
LOCATION			×	×	×	×	×			×	
SAFETY			×	×	×	×	×			×	
INSPECTOR	SCOTT	SCOTT	SCOTT SMITH	SCOTT	SCOTT	SCOTT	SCOTT	SCOTT	SCOTT	SCOTT	SCOTT
DATE	09/14/09	09/23/09	10/06/09	10/14/09	10/20/09	10/26/09	11/02/09	11/11/09	11/12/09	11/24/09	11/30/09

	SMITH				
12/04/09	SCOTT			×	FRAC CREW ON LOCATION
	SMITH				
02/05/10	STEVE	×	×	×	
	MCGLASSON				
03/12/10	STEVE	×	×	×	
	MCGLASSON				
03/29/10	STEVE	×	×	×	
	MCGLASSON	·			
04/12/10	FREDDIE	×	×		
	MARTINEZ				ï
04/21/10	FREDDIE	×	×		CONTACT FLINT TO FIX FENCE
	MARTINEZ				
05/03/10	FREDDIE	×	×		CONTACT FLINT TO FIX FENCE
	MARTINEZ				
05/05/10	FREDDIE	×	×		
	MARTINEZ				