Deviation Report			
Name of Company Burlington Resources Oil & Gas Company	Address P.O. Box 4289, Farming	ton, NM 87499	
Lease Name and Number (API Number) HOUCK #3M (30-045-30792)	Location 1295 FNL -1980 FWL	Sec. Twn. Rge. 12-029N-010W	
Pool and Formation Blanco Mesaverde/Basin Dakota	County SAN JUAN	State NEW MEXICO	

	(OH)	
Depth (ft)	Deviation (degrees)	
12	0.00	
151	0.25	
629	0.25	VE 6 7'00
1,130	0.25	A 10 / 0 9 2
1,630	0.75	
2,130	0.75	DEC 2002 RECONS. DIV.
2,440	1.00	DEC 2002 FRECONS. DIV. 1137 COM COIST. 3
6,283	1.75	FILL DIV. E
6,493	2.00	Se Contra 57
6,743	1.75	District Control
7,020	2.00	
		27 17 Stallar
Air Hammer Used? YE\$ / 1	NO	TO TO TO THE TOTAL PROPERTY OF THE TOTAL PRO

I, the undersigned, certify that I, acting in my capacity as Petroleum Engineer for Burlington Resources Oil & Gas Company, am authorized by said Company to make this report; and that this report was prepared under my supervision and directions, and that the facts stated herein are true to the best of my knowledge and belief.

Subscribed and sworn to before me this 3rd day of December, 2002.

Notary Public in and for San Juan County, New Mexico

My commission expires September 15, 2004.