



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 10 MAR 2011 Operator LIVELY API # 30-045-21579

Property Name LIVELY Well No. 25 Location: Unit L Section 29 Township 30 Range 8

Well Status (Shut-In or Producing) Initial PSI: Tubing 132 Intermediate 0 Casing 132 Bradenhead 1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min		0	132		132
10 min		0	132		132
15 min		0	132		132
20 min		0	132		132
25 min		0	132		132
30 min		0	132		132

FLOW CHARACTERISTICS

BRADENHEAD	INTERMEDIATE
Steady Flow ☒	
Surges ☐	
Down to Nothing ☐	☒
Nothing ☐	
Gas ☐	☒
Gas & Water ☐	
Water ☒	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 1

INTERMEDIATE

REMARKS:

B/H WHEN OPENED WATER BEGAN TO FLOW IMMEDIATELY WITH A GUSH
FOLLOWED BY STEADY FLOW, INTERMEDIATE BLEW DOWN TO
NOTHING IN 2 SECONDS

By [Signature]
[Signature]
(Position)

Witness [Signature]

E-mail address _____

