



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 3-23-11 Operator ConocoPhillips API #30-0 39-20644
Property Name San Juan 28-764 Well No. 186 Location: Unit Section 13 Township 28 Range 7
Well Status (Shut-In or Producing) Initial PSI: Tubing 44 Intermediate 59 Casing 49 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead	Csg	Int	Csg
TIME					
5 min		<u>0</u>	<u>48</u>	<u>0</u>	<u>48</u>
10 min				<u>0</u>	<u>47</u>
15 min				<u>0</u>	<u>46</u>
20 min				<u>0</u>	<u>46</u>
25 min				<u>0</u>	<u>46</u>
30 min				<u>0</u>	<u>47</u>

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	<u>✓</u>
Surges	
Down to Nothing	
Nothing	<u>DIST. 3</u>
Gas	<u>✓</u>
Gas & Water	<u>OIL CONS. DIV.</u>
Water	<u>RCVD MAR 23 '11</u>

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 5

REMARKS:

Bradenhead nothing when opened.
Intermediate Med blow first 3 minutes to light blow in 5-
Steady flow rest of 30 minute test

By Jean Tuth
Production Engineer
(Position)

Witness Monica Trechling

E-mail address

Request a gas analysis
gas analysis shows same gas as casing