Submit One Copy To Appropriate District Office State of New Mexico	Form C-103
<u>District I</u> Energy, Minerals and Natural Resources	March 18, 2009
1625 N. French Dr., Hobbs, NM 88240 District II	WELL API NO. 30-045-25040
1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION	5. Indicate Type of Lease
District III 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410	STATE FEE
District IV Santa Fe, NM 8/505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	V-100
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	State Com 31 8
1. Type of Well: ☐Oil Well ☐ Gas Well ☐ Other WW	8. Well Number 1
2. Name of Operator	9. OGRID Number
Burlington Resources Oil & Gas, LP	14538
3. Address of Operator	10. Pool name or Wildcat
P.O. Box 4289, Farmington, NM 87499-4289	Basin DK/Blanco MV
4. Well Location	
Unit Letter: M : 905 feet from the South line and 790 feet from the West line	
Section 2 Township 31N Range 8W NMPM	
11. Elevation (Show whether DR, RKB, RT, GR, etc. 6604 'GL	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR	
TEMPORARILY ABANDON	
POLL ON ALTER CASING	1 308
OTHER:	eady for OCD inspection after P&A
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.	
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the	
A steel market at least 4 in diameter and at least 4 above ground level has been set in concrete. It shows the	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR	
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR	
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
☐ The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and	
other production equipment.	
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.	
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with	
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location.	
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have	
to be removed.)	
All other environmental concerns have been addressed as per OCD rules.	
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC retrieved flow lines and pipelines.	RCVD JUL 15 '10
retrieved flow filles and pipeffiles.	OL CONS. DIV.
When all work has been completed, return this form to the appropriate District office to schedule an inspection.	
CHONATURE DOOM A GIMONIAL ATTERED BY	$\sim 1/2/D$
SIGNATURE AND CHOOOL TITLE. Regulatory Technic	1an DATE ///0//0.
TYPE OR PRINT NAME Jamie Goodwin E-MAIL Jamie.L.Goowin@con	
For State Use Only	
APPROVED BY: What I TITLE INSPECTOR	2 75-11
	2 DATE 3.25-1\
Conditions of Approval (if any):	

K