



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III3/district.htm](http://emnr.state.nm.us/ocd/District%20III3/district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-1-11 Operator D Simmons API #30-0 39-27556
Property Name Byrne 24 Well No. 1R Location: Unit Section 24 Township 25 Range 3
Well Status (Shut-In or Producing) Initial PSI: Tubing 60 Intermediate N/A Casing 60 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min			<u>60</u>		
10 min			<u>60</u>		
15 min			<u>60</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>RCVD APR 1 '11</u>
Nothing	<u>OIL CONS. DIV.</u>
Gas	<u>DIST. 3</u>
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

Blew down in 2 seconds- this well has a line
at 5000- the valve that looks like an intermediate
is not- it is actually an extra valve that is not needed. Shows
some thing as casing.

By [Signature]
Field Tech.
(Position)

Witness [Signature]

E-mail address