

**UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT**

RECEIVED**MAR 18 2011**

Sundry Notices and Reports on Wells

Farmington Field Office
Bureau of Land Management

1. Type of Well
GAS

5. Lease Number
SF-078622
6. If Indian, All. or
Tribe Name
7. Unit Agreement Name

2. Name of Operator
BURLINGTON
RESOURCES OIL & GAS COMPANY LP

3. Address & Phone No. of Operator

PO Box 4289, Farmington, NM 87499 (505) 326-9700

8. Well Name & Number
Luthy A 1

9. API Well No.
30-045-06040

4. Location of Well, Footage, Sec., T, R, M

Unit H (SENE), 1980' ^NF&L & 510' FEL, Section 1, T26N, R8W, NMPM

10. Field and Pool
South Blanco PC
11. County and State
San Juan, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment

Type of Action

☒ Abandonment

☐ Recompletion

☐ Plugging

☐ Casing Repair

☐ Altering Casing

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut off

☐ Conversion to Injection

☐ Other --

13. Describe Proposed or Completed Operations

The subject well was P&A'd on 2/23/11 per the attached report.



14. I hereby certify that the foregoing is true and correct.

Signed Crystal Tafoya Crystal Tafoya

Title: Staff Regulatory Technician

Date 3/16/11

(This space for Federal or State Office use)

APPROVED BY _____ Title _____ Date _____

CONDITION OF APPROVAL, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

ACCEPTED FOR RECORD**MAR 21 2011****NMOCD****FARMINGTON FIELD OFFICE**

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979

Farmington, New Mexico 87499

505-325-2627 * fax: 505-325-1211

Burlington Resources Oil & Gas Company LP

February 24, 2011

Luthy A #1

Page 1 of 1

1980' FSL & 510' FEL, Section 1, T-26-N, R-8-W

San Juan County, NM

Lease Number: SF-078622

API#30-045-06040

Plug and Abandonment Report

Notified BLM and NMOCD on 2/18/11

Plug and Abandonment Summary:

- 2/18/11 MOL. RIH with 3.5" gauge ring and tag fill at 2127'. Steve Mason, BLM, approved procedure change. RIH and set 3.5" wireline set CIBP at 2126'. Load casing with 18 bbls of water. RU Basin Wireline. Run CBL from 2126' to surface. TOC at surface. RD Basin. ND wellhead. NU swedge, collar, tubing head, companion flange and BOP; test. SI well. SDFD.
- 2/22/11 Open up well; no pressures. TIH and tag CIBP at 2126'. Pressure test casing to 800 PSI. RU cement equipment.
Plug #1a with CIBP at 2126', spot 17 sxs Class B cement (20.06 cf) inside casing from 2126' up to 1716'. Centrifugal pump broke down in middle of Plug #1. Replace pump.
Plug #1b spot 16 sxs Class B cement (18.88 cf) from 1700' to 1344' to cover the Pictured Cliffs interval through the Ojo Alamo top.
TOH with tubing. RU Basin Wireline. Perforate squeeze holes at 412'. Establish circulation out bradenhead.
Plug #2 spot 76 sxs Class B cement (89.68 cf) down 3.5" casing from 412' to surface, circulate good cement out bradenhead and casing.
SI well and WOC. ND BOP and flange. Dig out wellhead. SDFD.
- 2/23/11 No well pressures. Issue Hot Work Permit. Cut off wellhead. Found cement down 73' in 3.5" casing and at surface in 5.5" casing and down 30' in 9-5/8" casing.
Plug #3 spot 36 sxs Class B cement (28.32 cf) to top off casing, annulus and install P&A marker. RD. MOL.

Jim Yates, Synergy, was on location.

John Hagstrom and Kelly Nix, BLM representatives, were on location.