



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrdr.state.nm.us/ocd/District III/3district.htm](http://emrdr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT


(submit 1 copy to above address)

Date of Test 4-APR-2011 Operator CONOCO API #30-0 45-2822
Property Name SAN JUAN 32-8 Well No. 200 Location: Unit _____ Section 24 Township 31 Range 8
Well Status(Shut-In or Producing) Initial PSI: Tubing 0 Intermediate _____ Casing 55 Bradenhead 2

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min		<u>1</u>	<u>SS</u>		
10 min			<u>SS</u>		
15 min			<u>SS</u>		
20 min			<u>SS</u>		
25 min			<u>SS</u>		
30 min			<u>SS</u>		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow _____	_____
Surges _____	_____
Down to Nothing _____	_____
Nothing _____ ✓	_____
Gas _____	_____
Gas & Water _____	_____
Water _____	_____



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 1

INTERMEDIATE _____

REMARKS:

BRADEN HEAD ON VACUUM. OPENED BRADEN HEAD NOTHING
CAME OUT

By [Signature]
MSO
(Position)

Witness [Signature]