



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III3district.htm](http://emnrd.state.nm.us/ocd/District%20III3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)


Date of Test 4-APR-2011 Operator COND O API #30-045 31085
74602

Property Name SAN JUAN 32-8 Well No. 104 Location: Unit ___ Section 4 Township 3 Range 8

Well Status (Shut-In or Producing) Initial PSI: Tubing 67 Intermediate 8 Casing 103 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

	PRESSURE				
Testing	Bradenhead		INTERM		
	BH	Int	Csg	Int	
TIME					
5 min		67	103		115
10 min		18	109		116
15 min		12	112		116
20 min		0	112		116
25 min		1	112		116
30 min		3	113		116



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ___ FRESH ___ SALTY ___ SULFUR ___ BLACK ___

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

OPENED BRADEN HEAD NOTHING CAME OUT. CASING PRESSURE
CLIMBED TO 113 ON B/H TEST. OPENED INTERMEDIATE
AND BLEW DOWN NOTHING. CASING CLIMBED AND HELD AT 116

By MSO

(Position)

Witness [Signature]