



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-APR-2011 Operator CONDO API #30-0 45-3372
Property Name SAN JUAN HILL 30-8 Well No. 15M Location: Unit Section 24 Township 31 Range 8
Well Status (Shut-In or Producing) Initial PSI: Tubing 107 Intermediate 13 Casing 541 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM		
	BH	Int	Csg	Int	Csg	
TIME						
5 min		<u>-1</u>	<u>541</u>		<u>541</u>	
10 min		<u>-1</u>	<u>541</u>		<u>541</u>	
15 min		<u>-1</u>	<u>541</u>		<u>541</u>	
20 min		<u>-1</u>	<u>541</u>		<u>541</u>	
25 min		<u>-1</u>	<u>541</u>		<u>541</u>	
30 min		<u>-1</u>	<u>541</u>		<u>541</u>	

FLOW CHARACTERISTICS
BRADENHEAD INTERMEDIATE

Steady Flow

Surges

Down to Nothing ✓

Nothing

Gas

Gas & Water

Water



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS:

1 SECOND BLOW DOWN ON BRADENHEAD WHEN OPENED,
OPENED INTERMEDIATE NOTHING CAME OUT WAS ON VALVE,

By [Signature]
WGO
(Position)

Witness [Signature]