



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-11-11 Operator Burlington Res. API #30-0 4526222

Property Name Taylor Com Ltd Well No. 2A Location: Unit Section 17 Township 30 Range 11

Well Status (Shut-In or Producing) Initial PSI: Tubing 236 Intermediate NA Casing 236 Bradenhead 119

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min			<u>236</u>		
10 min			<u>237</u>		
15 min			<u>237</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>/</u>
Nothing	
Gas	
Gas & Water	
Water	



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE NA

REMARKS:

Hard blow fast to seconds to vapor in 1 minute

Re-test in one year

By DSL

Witness Monica Kuehling

(Position)

E-mail address

After reviewing well file:
Please submit schematic
This well will need retested
in one month. (May 2011) MLC