NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-13-11 Operator Burlington Res API #30-0 39-07657

Property Name San Juan 29-7 Ut Well No. 80 Location: Unit ___ Section 9 Township 29 Range 7

Well Status(Shut-In or Producing) Initial PSI: Tubing 104 Intermediate 53 Casing 215 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE Bradenhead BH	Bradenhead Int	Bradenhead Csg	INTERM Int	INTERM Csg
TIME 5 min				0	216
10 min				0	216
15 min				0	220
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	✓	✓
Nothing		
Gas		✓
Gas & Water		
Water		

RECEIVED APR 2011 OIL CONS. DIV. DIST.

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ____ FRESH ____ SALTY ____ SULFUR ____ BLACK ____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS: Says Shallower is BH - Hooked up on this well - Puff on BH when opened. Int. dead at 6 seconds -

By Mike Murphy
Specialist
(Position)

Witness Monica Kuehling

E-mail address ____