



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emmr.state.nm.us/ocd/District III/3district.htm](http://emmr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-25-11 Operator Burlington Res API #30-0 45-09606
Property Name Suave Glenn Well No. 1 Location: Unit 8 Section 8 Township 30 Range 11
Well Status (Shut-In or Producing) Initial PSI: Tubing 186 Intermediate 186 Casing 316 Bradenhead 8

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
5 min			316		
10 min			316		
15 min			316		
20 min			316		
25 min			317		
30 min			317		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>DIST. 3</u>
Nothing	<u>OIL CONS. DIV.</u>
Gas	<u>RCVD APR 25 '11</u>
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 1 INTERMEDIATE _____

REMARKS: Black mud first 20 seconds. w/ musty gas / starting
gurgling out black gook at 4:15 - nothing made it to hose at 5:20.
Nothing in bucket at 10 - 15 - 20 - 25 - 30 gurgles after 5-min shut-in
By MSO (Position)
Witness Monica Kuehling

E-mail address _____