



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 11-MAY-2011 Operator CONCORDIA/BLVD/2011 API #30-0 39-07671

Property Name 29-7 UNIT Well No. 824 Location: Unit B Section 4 Township 29 Range 7

Well Status (Shut-In or Producing) Initial PSI: Tubing 132 Intermediate 5 Casing 103 Bradenhead 1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min		<u>7</u>	<u>103</u>		
10 min		<u>7</u>	<u>103</u>		
15 min		<u>7</u>	<u>104</u>		
20 min		<u>7</u>	<u>105</u>		
25 min		<u>7</u>	<u>106</u>		
30 min		<u>7</u>	<u>107</u>		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>✓</u>
Nothing	<u>✓</u>
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ✓ FRESH ✓ SALTY ✓ SULFUR ✓ BLACK ✓

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

BRADEN HEAD HAD NOTHING ON IT

INTERMEDIATE BLEW DOWN TO NOTHING

By Craig Meador

Witness John Doe

(Position)

E-mail address _____

