



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 11-MAY-2011 Operator CONOCO/BILLINGEN API #30-0 39-21623
Property Name SAN JUAN 29-7 UNIT Well No. 79A Location: Unit C Section 5 Township 29 Range 7
Well Status(Shut-In or Producing) Initial PSI: Tubing 124 Intermediate Casing 131 Bradenhead 0.5

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min			131		
10 min			131		
15 min			131		
20 min			131		
25 min			131		
30 min			131		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	✓
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0.2

INTERMEDIATE X

REMARKS:

GAUGE SHOWED VACUUM

By Craig Meador
[Signature]
(Position)

Witness John DeHart
[Signature]

E-mail address

