



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 11-MAY-2011 Operator CONOCOPILLMANN API #30-0 39 577/D

Property Name SAN JUAN 29-7 Well No. 90 Location: Unit B Section 5 Township 29 Range 7

Well Status(Shut-In or Producing) Initial PSI: Tubing 139 Intermediate 1 Casing 145 Bradenhead 1.3

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				FLOW CHARACTERISTICS	
	Bradenhead		INTERM		BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg	
TIME						
5 min		.4	146		142	
10 min		.4	144		146	
15 min		.4	146		146	
20 min		.4	146		146	
25 min		.4	146		146	
30 min		.4	146		146	

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 1

INTERMEDIATE 0

REMARKS:

GAGE ON BRADEN SHOWED VACUUM
INTERMEDIATE BLEW DOWN TO NOTHING IN LESS THAN
1 SECOND

By Craig Meador
(Position)

Witness JOHN DURHAM
John Durham

E-mail address _____

