



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrds.state.nm.us/ocd/District III/district.htm](http://emnrds.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test 10-18-10 Operator EnerVest API #30-0 3921185
Property Name Apache 127 Well No. 115 Location: Unit M Section 3 Township 24N Range 4W
Well Status(Shut-In or Producing) Producing Tubing 20 Intermediate NA Casing 60 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	INTERMEDIATE	CASING		
5 minutes	<u>NA</u>	<u>60</u>	Steady Flow	<u>NA</u>
10 minutes	<u>/</u>	<u>60</u>	Surges	<u>/</u>
15 minutes	<u>/</u>		Down to Nothing	<u>/</u>
20 minutes	<u>/</u>		Nothing	<u>/</u>
25 minutes	<u>/</u>		Gas	<u>/</u>
30 minutes	<u>/</u>		Gas & Water	<u>/</u>
			Water	<u>/</u>

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE NA

REMARKS:

NO Bradenhead pressure 0

By Leonard Luevano

Witness _____

Rumper
(Position)

